X reset CIM. over 5/8" rod by projecting 1/4 lines from East (Sec. 22) 8-7-1975 & intersecting N-S Sec. Line. (1)

1/4 Corner 21-22 Cascade 107-14

Note: Set T. Hunter BK 5 p. 102 for Notes in Sec. 22

Much Confusion at this Corner in I.B.M. property.

#1742206

P.C. Compton - 1863 apparently used This 1/4 Corner To set Center at inter. lines

J. Kerr indicates 1/4 Cor. M. & L. but there is a possibility That his notes might be in error. as he mentions msmt of 2680 To South which is close To what it is now.

McGhie in 1955-56 has notes To indicate they talked To Kerr who Told Them he set Center 22 and a mark on W. 1/4 line Sec. 22 on E. side of T.H. #52 McGhie projected This line West & intersected the

N-S Section line of N.W 22 To So. 22
This was 1/4 corner location used in the IBM
Survey by McGhie.
Then either McGhie or Sankstone set a Cast i
Mon. at or near The Corner used in IBM Surv

Aug. 1975 - Co. Surv. - extended 1/4 line by Elec. Tra
from E. 1/4 Cor. Sec. 22 (a broken Top - CIM) over The Cen
Sec. 22 - (notches cut in M.H. ring at intersected poin
and intersected N-S Sec. line again (by Elec. Tra
Removed former CIM & rod under it. and set CIM
at our Location which moved former location
0.28' South & 1.98' East, on Aug 7, 1975.
Govt Notes [illegible]
40.00 Set 1/4 Sec. [illegible]
Pits. [illegible]

1/4 CORNER 21, 22 CASCADE 107-14 (2)
6/26/90 FD CIM ON IBM GROUNDS IN GOOD
COND. POST & SIGN ± 1' WEST #742206