X 7-6-1970 set C I M over orig stone and 5/8 x 2' rod flush in blacktop (1)

1/4 Corner 3-11-81 Reset 10" C I M. 17 - 20 Kalmar 107-15

#751704

5-1874 Hunter P 253 No 253 S 20 W Hamilton N Groner.
found stone in center road - B trees gone. accepted acco.
— 1/16 east set stake M & L 19.90 1/2.
— 1/16 south set stone 2 x 6 x 18 M & L 20.00
— Meas west 40.12

6-1885 Hunter P 397 No 387 S. 17. D L King, etal.
found stone P 253 anered by Mr. Middleton as
place where original stake stood.
— 1/16 north set stone in center road M & L 19.89 1/2.
bearings at corner N 1/4° E — N 89° 50' E (1313.07'

(over)

Co Hwy Dept. 1937 B84. Sta 106+02.5 at corner.
found pointed limestone
- mear South 2635.0 -
Lg 14" oak
Hub
Willow.

2.8'N - 1.4'W of PI 0°20' left ↑N

Logs of fences E & W 106+04.0

1/16 stone near midway. 5' west of corner

NW 62.4 erected by farmers. Jensen set
W 53.3 Fraser set stone 5' west true line B84D73 witnesses -
NE 48.5 -

PI north near 1/16. Sta 120+43.0
cross west culv hdwl. NW. 23.7 — cross in east culv. hdwl. NE 20.5
- 1/16 cor south found recorded stone - RPS B84D73 4"x 8"x12"
Oak tree NE 45.0 - Oak tree SE 50.0 - Stump east 38.0
this stone erected by a Mr Jensen to be 5' west of true line. so set nail 5' east of stone. Turn line north to locate 1/4 17-20 a square nail a temp location of corner. 14" oak NW 65.0 willow NE 50.1.
- later found pointed L stone as 1/4 17-20 2.8' N and 1.4' W of nail about above tree now true tree.

#751704 (2)

Card # 2 1/4 17-20 Kalmar 107-15E

7-6-1970 Co surv. Meas from fence line west (rail set) North 1317 and 2634. (set in cross) R 1313.07 and 1326.14. Meas south 1317.5 (Co meas for 1/2 of full 1/2 mile) after 1/4 17-20 stone found set PK as 1/16 which came 7' east of center road. - set 10" bridge spike 33' east on eyeball line with north side small bldg (near pump house) RP 1/16 90.04 NE To NW cor house with 20" oak on line. RP bridge spike 33' east - 2.4' S of old post hole depression in lawn. - 65.8 to NW cor house with enormous oak 30" on line (West edge) - 69.5 to SE cor house (rotten sills)

PK set on exact line to center C/M L20 (over for 1/4 cor)

dug 2'x3' hole in black top found 3-10" bridge sp.
at various depths as risers above stone, varied slightly in
reference. found stone with 2"x8" top 4.3' below surface.
set iron plate (sawed off hanger) with 5/8"x2' rod under.
below C i N placed flush with surface.
- corner came 0.4' south of 00 nail in center road in
line with main fence west & east.
- tadd nail in 24" oak up 7' on NE side - NW 61.9
- center of zero in number plate of PP# 22098, SSW 101.6.
- 3/8" x 3' rebar up 4" under N side woven fence W 90.0
RP to rebar NE 45' ± to center above 24" oak.
4-1911 Ch Larson P 152 B L 20 for E Arnold. found corner
set 1/16 south 3x18x24 N & L 1320' To center 20 a L stone
found 4x16x20. - Center NE 1/4 20 set holes flue as corner
19.90 1313.4 west to line 19.98 1318.68 S To car post

Kalmar 1/4 corner 17-20 #751704 13

Cal'l Waters Karnak 1557

40.00 Set temp 1/4 steel post

West on true line between Sec 17 + 20

40.00 Set 1/4 steel post V. 0°15'

Bur Ont C N 2 W 62

" " 6 5 49 E N 5

6-2-1980 (1980 Remon Bk Page 52) Removed CIM prior to road grading and set 2 - 1" x 35" square iron on line to the East.

1st iron is 163.36 East

2nd iron is 312.26 East

3-12-81 (1981 Remon BK) Set a 10" CIM over tamper base with pipe on it. Reset 10" CIM from iron set to the East prior to road grading. Took 1 new R.P. CSD in p. #22098 SW 101.52 Corner now fall on the west shoulder of the new road