8-31-70 dug area in blacktop left C.rod as found. (1) 2

X Set C.I.M. 4-8-71 over rod in place (took R.P.'s

1/4 corner south 1/4 32 Kalmar 107-15-

north 1/4 5 Salem 106-15.

#753204

5-1871 Perry P162 No 185 S 29-30-31-32

found stone monument axes placed on orig corner.

B bars and fence corners test stone.

6- 1886 Hunter P412 No 401 S 32. S. Hicks

found stone center crossroads P162.

-1/16 east found stone M & L. 19.92. 1314.72 exactly.

April, 1861 Samuel McDowell Pg. 66 No. 93 used 1/4 Corner

from Prop. Survey in S.E. 1/4 Sec 32 & N.E 1/4 Sec. 5

over)

5/8" rod in blacktop assumed by Co Hwy Dept or McGhie.

Lp corner fence post — NW 51.8.

Disc " " " — NE 48.2.

Bent spike in 18" elm — SW 48.75.

This corner incorrect no stone ever found. could be replaced accurately by finding stone 1/16 east in township road. and projecting from C1M at Southeast corner 32, 7-7-To Co Surv. ran direct transit line C1M SE 32 To iron 5/8" rod above. Meas 2626.56 R. 2629.44 set nail on line at 1/16 wr. eyeball line west edge pole N and for pole line at 31.61 To ground wire staple on pole. this came at 1310.1 from iron pin at S 1/4 32. 1/16 fence south has brushy end but comes to 2' east. road cut on S side, 50-50 chance only stone could have survived.

see Card # 2.

#753204 (2)

Card #2 S 1/4 32 Kalmar 107-15
— 1/16 exact — N 1/4 5 Salem 106-15

8-28-70 dug with tractor entire area where corner could be. found perfect limestone, lying flat. triangular shape pointed to 4" wide chisel point likely 8" at base, 12" long. lay in exact area assumed corner should be. about 2.53' east and 1.2 north of nail set making 1313.93 east C/M 1312.63 west to rod.
set 5/8" x 2' rod at center of northing of stone and midway 1313.28 to bold point. will dig in black top 2.4' north and slightly west of co rod.
RP to 1/16 30.52' to staple 18" up on ground wire on E side pole.
old ke 31.61 directly north - tie now 2.5' west of north.

8-31-70 dug in blacktop large enough to check entire area where stone corner have been. found area covering rod in place dug extensively in times past likely by county. had to probe that area. old road well down, worn away stone gone or spot where it lay destroyed by previous digging.

over.

had no choice but to accept rod as true corner
will set C.I.M. & re reference, set 5/8 x 2' rod 20" down.
- re set 1/16 east with 1/2" x 3' rod M & L. 1313.28 R 1314.72
corner now 3' east of PP north all the lines exactly with rest
of poles further north. placed stone found on N side 18" deep.
- slightly north of ℄ road 18" ±
31.63 to bottle cap on E side pole just south of ground wire.

R.P's to C.I.M.

Co. Surv. disc in P.P.		N.E.	86.38
Punch hole in ~~N~~ N. end of Road C.M.P. (18")		N.E.	35.03
" in. So. end of 18" C.M.P. (Road E)		S.E.	35.85
" in. So. end of 18" C.M.P. (Road W.)		S.W.	29.67
" in. North end of 18" C.M.P. (Road W)		N.W.	33.52

Cor's Notes, Kerrick 1954
40.00 set [illegible]
BIK Oak 14 West 45 links
dug from

(753204)
(37)

6-4-93
MW. RF. AE

So. 1/4 32 107-15 Kalmar
fd CIM 5" deep in Center Int.
CR # 5 & Frontier Road.

Set Ref pipe NE of Corner
50' North of ℄ Frontier Road ℄
44'1/2' East of ℄ CR # 5

To Ref pipe
x2+ P.K in PP # (NO #) (2nd pole
east of Corner on north side Frontier
Road to S1/4 32 107-15

129°52'58"	131°16'24"
0°00'44"	1°24'06"
129°52'14"	129°52'18"

To S1/4 32 (CIM)
VA 86°40'04"
Slope 64.775 Hor 64.67

NO. 447
NATIONAL PRINTRAST