~~8-1-1961 C/M over iron rod set by Co H Dept~~ (1)
8-8-83 CTM
Section corner 23-24-25-26 Palm. 108-13
#832405
11-18 77 Hunter P323 no 317 L24 L DeWitz
Corner missing, would have used to set line
for 1/4 23-24 if in place

Co Hwy Dept. B2 Meas west. 5279.63.
Meas east 5274.28 to c.line.
had iron rod ac corner - set C/M over rod.
hub NE 87.82.
" NW 84.71.
Disc tele pole NW ~~57.1~~ June 1983
Disc P Pole. SE 57.68
over 1 Kar

J Kerr 10-15-1923-1946 book 32 pages 27-28-29.
Page 28. 1" square head bridge bolt 13" long.
Sp PP SE 45.5 - Sp TP NW 45.0 - Sp cor fd F NE 53.0.
- Mean west 5278.7 to 1" shaft 2' long. in Co road.
- N 1/4 26 1" pipe 1.8" long 2639.35 set M & L lately.
- E 1/4 26 1 1/4 x 30" pipe 3' S fence west. - 22.3' E road fence
at M & L 2640. or 5280 for mile S to Limestone with
1 1/4" pipe riser
No search for corner at 25-26 used by Hunter 1886.
Did not find iron set by Hunter at SE 26 driven deep.
Hunter had 39.96 1/2 for mean E 1/4 26 to SE 26. 2637.69.

Set by William Perby 5-1854
80.00 set post cor to sec 23, 24, 25 & 26 in a mound of Earth & Sod deposited
charcoal made trench & pits planted Osage Orange Seed SW & SE

#832405 (2)

Section Corner 23-24-25-26, Farmington, 108-13

6-14-83, Sec. Cr. 23-24-25-26: Found C.H.D CIM down 14" in ℄ E-W Hacktop road and 2' West ℄ N-S crushed rock road. Broke head off CIM with pickhammer. Old CHD disc in pp 19936 still in place OK.
New RP's: C.S. Disc in SW side pp # 19936
SE 57.62
CS Disc in NW side Telephone pole
SW 59.02

7-19-83, Sec. Cr. 23-24-25-26: Removed CHD CIM and found it set on a 120d spike. Dug from a point 2½' North and 2' East of the CIM location, South for

9½' and West 9'. We were concentrating digging SW'ly since this is area of prorated Govt location using fence at ¼ Cor 23-26 (appx 6½' South and 5' West) Found "Kerr" 1" Bridge bolt 3.8 West and 4.7 South (of the CIM loc), 2½' deep and in a crushed rock road. Someone had dug at the East end of the hole — probably the 1930 CHD since we found a 1"x2" hub at that level (top down 5½') and on the W'ly side of their dig 2.31 South and .12 East of the CIM location. Found 2 pieces of hard coal or hard charcoal appx 1.0 East of the CIM location and in the clay beneath the old diggings. Probed North and East in the hole but found nothing. Dug an average depth of 7' however the South side of the hole had much more (1'+) black dirt than the North side (6") Found nothing further.

#832405 (3)

Section Corner 23-24-25-26, Farmington, 108-13

8-8-83, Sec. Cor. 23-24-25-26: Set a CIC/p^2 at location of hub found 7-19-83. The corner is 2' South of the ℄ of the E-W road & 2' West of the ℄ roads N & S. Also set a 3/4"x18" rebar back at the CHD CIM location for CHD P.I.

RP's: Punch hole in East end 18" C.M.P. NE 38.90
Punch hole in West end 18" CMP NW 38.00
CSD in pp # 19936 SE 55.66
CSD in telephone pole SW 57.02

8-3-93 Set 1" sq pipe w/cap on line to Red light on shortest of two radio towers South of corner CHD. PI Iron 2.2' North of C.I.C./p^2 over →

Ref pipe is 4' west of N-S ℄ of Twp Rd.

∡ @ Ref Pipe

To Sec Cor

VA 89°06'36"

Slope 107.55 Hor 107.54

∡ @ Ref Pipe

To ¾" Iron (CHD PI)

VA 89° 05' 12"

Slope 109.84 Hor 109.83

7-15-94 SET 1" SQ PIPE W/CAP @ 1993 REFERENCED LOCATION. THE CORNER FALLS 2' SOUTH OF ℄ CR #21 + 1½' WEST OF ℄ TWP ROS NORTH + SOUTH. THE 1983 TIES CHECKED TO CULVERT PUNCH HOLES, BUT POLE SE IS LEANING A BIT.