5-4-1972 set C/M over stone found. #833106 (1)

~~Removed C/M~~ 6-20-80 Set CIM

1/4 Corner west 1/4 31 Farm. 108-13

east 1/4 36 Arono. 108-14.

7-1917 J Kerr P 268 B L 31 Herman Meyere.

could find no corner, so set stone

M & L 2640 from engraved township corner and sec cor mark.

5-4-1972 Co surv. found 3" x 6" top limestone easily in newly graded road. set P 268 B with shoe sole sloped iron on top & slope down about 2'

- set C/M over stone with iron shoe sole on west side (tee up)
- C/M. quite close to surface but more rock will be added.
- Corner came about 2.8' E and 3.0 N of where corner was over

believed to be by 2640. Meas from township corner as now set. As original engraved monument was washed out one wonders if corner now in place is the same location at township Cor.

100' East to 1"x24" iron pipe a few inches S of new wooden fence. flush.

101.06 SSW to Cone nail in small knot on E side Pole. corner very slightly west of center newly graded road

---

Set by John Bull 10-1853
40.00 Set post for gr. Sec Cor. Job 2*
Burr oak 14 North 46¼ lks. & dug trench per instructions.
44.64 Burr oak 14 inches

5-18-76 Dug from ~~knot~~ CIM E 14'± to E edge of road. Dug 5' S and 3'+ N of Kerr corner. Dug to clay (3') found nothing. Removed CIM.

Power Dam Survey (1916) used E of road & E-W fence meas. South 2643.3

1/4 Corner West 1/4 Cor. 31 Farmington ② 108-13
East 1/4 Cor. 36 Oronoco 108-14

5-2-1980 (1980 Remon. BK) Shot 1/16th West and took several shots in the fence Note (Fence corner E-W-N) from tree.
#833106

6-6-1980 (1980 Remon BK) Dug with backhoe from a point 3' North of Ken (stone and scrap iron still in place) as per Power Dam Survey West for 15' and East 3'. Dug North and South from this point but hole very irregular. Dug 2' deep to clay. Found nothing. Condition bad at West end of hole.

W 1/4 Cor 31

6-20-1980 (1980 Remon. BK) W 1/4 Cor 31: Set a CIM back at Ken's location at intersection of Ken RPS (Pipe East and power pole SSW). Monument ~~in~~ site on

top of Kerr stone and came .1 West of the point shot here 6-10-1979 which makes corner .15 East of line.

RP's:

- Spike in South side Box Elder West 63.49
- Pipe on South side of fence East East 100.00
- Concrete nail in knot on East side pole SSW 101.06

Corner appx 3' West ℄ and in line with fence East and West.

12-3-96 FOUND CIM IN GOOD CONDITION 4" DEEP IN CRUSHED ROCK TOWNSHIP ROAD ± 3' WEST OF ℄.