1 9-1972. ~~set R R spike~~ as final corner to date. 5-23-1975 after finding 4 9-10 2.46' N. This Center Must Move 0.8' N. (1)

1/4 corner Center 10 Orono 10 8-14.
#841009

6-1902 H Fraser P42B L10 Oronoco town board
planted stone on true intersection lines
- meas north 2630.5.
- 16 east set stone M & L 1316.
- 16 west " " " 13 15.6.
- 16 south " " " 1323.5
- 16 center NW 1/4. (Caption 4-1904).
drone iron stake M & L on N-S 1/16 line. 1311.5.

5-1892. Chas Fraser P484 no 461 L10 John Wickliff
used corner set temp point south M & L 20.01.
- set point each - set boulder. 10 x 12 x 16 at 17.46 chains 22.46 to E 1/4 corner

Co Hwy Dept (no corner now)

Dead tele pole	NE	36.2
Spike power pole	NNW	56.9
Dead " "	S	84.0
- meas north to S 1/4 3		2627.7

1939 Co. H.D. BK113 P 71 indicates a rotted stake in earlier Survey and Ties taken as shown here ←

- Spike on tele pole north 300'± a 1941 bench mark 1113.89 feet elevation.

very deep fill - no corner in evidence all RPs but 1 gone. that may be changed.

5-5&7-1970 Co Surv. set 1/4 10-11 by NS line. then run inter direct lines. set 5/8" rod as corner (6 grade)

- found stake at 1/16 south after consulting John Kerr power dam survey

Topo - stake some 2' north and 2' east of corner post and fence line

- set 1/2" x 4' pipe with brass fitting on top - orig stake on south side oval boulder 5x6x8"± on north side. at 1/16 S of center 10.

Card #2 Center 10 Aronoco 10 8-14

#841009

(2)

9-1972 found 5/8" rod set 5-1970 on direct line betw 1/4 section corners N & S. as set by J Kerr and E-W 1/4 line from W 1/4 as C/M reset County HD R.P.S. and E 1/4 corner reset betw. large long and 4 rounded L stone at NE 10 and pointing 1/16 stone S of 1/4 10-11 and 1/3 mear. - found 1/4 3-10 orig stone 5.45 west and 2.65 North of J Kerr C/M set as corner.

- reset Center 10 - drove K R spike flush in blacktop to correct for change in above 1/4 3-10.

Mound west 1/2(5.45' or 2.72' as final corner unless 1/4 9-10 is further researched for corner west & north (over

8-11-72 Mena elec from rod set 5-1970 to C/M.
at 1/4 10-11 (final corner) 2627.40
when adding 2.72 makes meas exact 2630.12 (9-1972)
true mean measure 2629.82 computed as final cor O.K.
N side E 1/2 10 1972 2633.24 S side E 1/2 10 5-1969 2626.4.
No position RPS to date road north graded P Poles changed.
- did not re-check or change 1/16 corner south this
corner should be re-set exactly N & L

1939 C.H.D. Book # 113 page 77 Shows Rotten stake
From C.H.D. Book # 42 page 29