841404

¼ Corner 14-23 Oronoco - 108-14

Apparently no Courthouse records / see T. Hunter Bk 4 p. 100 notes on Sec. 23 - Jan. 1876

1916 Power Dam Survey drawings indicates no stone or Corner was found, they accepted midway ℄ line point for their work.

1929 J. Kerr Book 2 p 14-30 (Note: Kerr Took old Survey record data which was Indexed wrong - See mby To Bk 'A' page 25 shows ¼ cor. midway, but over 100 ft. So. of line between Section Corners. An examination of the Power Dam drawings indicates this corner Location To be in the Lake, So records unclear as To what may have been used To locate corner this far off line.

Page 15 indicates stone as Corner 1.55½ ch. So. of line

Kerr mistakenly Used Sec. 23-ORIG

over

3-1976 Co. Surv. - Computed Corner location based on Norton and Armstrong Plat, this placed Corner ± 48' South of the line between Sec Corners and 2.2' ——— East from the Midway Point

Govt Notes M. Kovacik 1894

40.00 Set temp 1/4 section post West on true line between sects.

40.00 Set 1/4 section post 14 ± 25, V 9° 41'

Jack Oak 6 S 42 W 82

Jack Oak 6 N 55 E 99