6-14-1967. set C/M. over 1¼ x 30" pipe (reproduced lines Lo.).
Reset C.M. - April 9, 1974 Correction of a corner (1)

¼ Corner. 21-22. Aronoco 108-14.

#842206

11-1894 W Fraser P555 No 512 S22 A. Krause.

Could not find any evidence or knowledge of corner.

set iron rod. M&L 39.74. (2622.84'

-16 south set stone M&L 19.87. (1311.42.

6-1967. J Kerr.

dug extensively for iron corner. rather steep grade from west to east. road reputed as having been badly washed out.

-16 south found ½ stone (found by recent surveyors, both near) drove iron beside ½ corner which lies under fence. no fences either east or west.

- meas from SW Cor 22. 1311.0

-over-

projected line from SW 22 over 1/16 north, doubled distance of 2622.0
set 1¼ x 30" pipe below CIM.
– corner lies 3'± north center present road.
– " " in perfect line with fence line north.
– 20D in hub on NW side 16" boxelder SW 87.1.
– Dies power pole. N 38.8

8-22-69 ~~removed CIM~~ Rec'd CIM 4-9-74 set ½" rod flush for grading
may not grade with road east-
– set rod on QZ to NE corner house, southeast ;
at 120.0' which came ∠ west edge of rock drive
then anchor 118' to NE corner front house. rod also
lies 96.4 to NW corner house (attached garage).

#842206

(2)

Card # 2. 1/4 21-22 Oroville 108-14.

Co H D B 326 1968. CIM lies 5.04' north of sta 157+23.70 at 90° from sta to corner. which would make meas cart to center 22 2604.09

Meas west to CIM measured on road ℄ and 90° angled to CIM 5261.33

New R.P.'s (4-16-74)

Disc on E. side P.P. # 39384
Co. Surv. Disc. top center 8" square Corner post
Punch hole top center W. end Field culvert

North = 40.00
South = 42.95
N.W = 33.16

(over)

This is a correction of a corner.
W. Fraser's iron was 0.9' South & 3.25' West
of J. Kerr's corner.
Reset a C.I.M. over a 1/2" rod over
W. Fraser's iron
Coast Metro M. Kavanagh 1954
40.00 Set 4" x 4" post in mound with
stones, pipes, charred stake and Orange
Crayon scribe N. & S. W.