8-28-74 Reset C.I.M. over original C.I.M.

9-14-1963 set C I M in place orig stone (1)
#842605

section corner 26-27-34-35 Aronoco 108-14
records not positive - unrecorded survey 6-1881
may have used corner. - limestone used by
Co Hwy Dept in line fence east has proved
in various ways to be true corner. accepted by
farmer & redrickx as true corner.
9-1963 J Kerr. used corner earlier survey(over).
set C I M in place of corner.

Disc -	power pole.	℄ E	46.28.
spud.	tele pole	℄ W	58.2.
spud	" "	S S W	61.4.
steel corner	fence post	S W	48.6

-over-

- Meas south 5264.2 to SE cor 34. Corner set as 1/4 34-35 not correct, may have set present corner M & L. - Must rerun E-W 1/4 line to set true 1/4 34-35.

- West on 4-1967 aerial line run from. NW 34 to NE 34 which showed N 1/4 34 8.82' north of direct line which accounts for excessive length of N 1/2 of N-S 1/4 line 34

6-1934. J Kerr. on digging in area in presents of farmer & redrick found what all assumed considered as corner. set limestone later found as corner.

New Additional R.P.'s
Cor. lies 3.0' South & Road West + in ℄ North-South Road

C.S.P. S.W. side P.P.	N.W.	107.58
Top Center 6" sq. tele box	S.W.	48.38

P.D. Survey (1916) found stake

Oronoco section corner 26-27-34-35 (2)
Gov't Works M. Kinnick 1854 #842605
80.00 Set post for corner to section
26-27-34-35 Erected mound w. 16
trench, pits, charcoal stake & Osage
Orange Scrats at each angle