#851404

1/4 Corner 14-23 New Haven 10 8-15
12-1894 H Fraser P557 No 513 S10-11-14-15 6 parties.
located temp point midway on section line for line north.
Midway would be 40.24 5/6 (2656.4' No meas north as
corner not placed on line.

1947 J Kerr B 34 P 40 S14 H Lehman.
Run south section line SW 14 east. 5302.5 R 5312.8
- set 3/4" square bar at 660'
- set axle shaft at 3976.68
- found stone small LS on top of larger L.S below at SE 14
- set old well point with 1" pipe riser at SE 14.

-over.

ded not locate or set perm. corner at 1/4 14-23
apparently no river crossing in area.

3-1973 McGhie & Betts Inc.
found iron shaft inplace - possibly by J. Kerr -
as they also found several irons along the Sec line
left corner inplace

Gov. Notes- Cushing, Dept. Sur, 6-12-1854.
West on true line between 14 and 23.
40.00 Set quarter section post.
Aspen 10 in. N56W 30 lks.
Aspen 30 in. S56W 23 lks.
80.00 Section.corner.

12/14/90 Vince Fangman Found 1" PTO shaft leaning/
hit in recent grading Adjusted up, reset a d.5K
blade with 8" hole in center around mon. set.
fiberglass post. RP's 30d spk in 10" Elm ESE 12.06
3/4" pipe north on 1/4 line 66.00; 30d spk in 10" chinecse elm WSW 12.50
3/4" pipe NE 92.81