X 6-19-1970 set C/M over orig iron bolt, glass, lime
section corner south 32-33 New Haven 108-15.
north 4-5 Kalmar 107-15.
#853305 (1)
4-1875 Hunter B 269 no 267 L 32. S Malcom & others 3.
found hole made by orig stake from stumps & all B trees
with marks still plain. set new stake in its place.
run & staked line entire mile N-S 1/16 line E 1/2 L 32.
-16 west set stake M & L 19.89 1/2. (1313.04

4-1905 Robt Fraser P 180 L 33 W Lake, D Altman, S Searles
found old stake pointed in clean clay covered by all present
as correct. Meas L 1/4 33 to 1/16 west 27 3/4 lks (18.31 short
which brought corner within 1/2 L stake
-drove iron gas pipe as corner 3' N and 1/2 rods west L willows
-east drove oak stake at 9.95 13/16 (657.235
over.

then oak stake as 1/16 corner N & L another 9.95 13/16 (657.2
then oak stake at 1244 49/64 (821.5
then 946 56/64 (492.9 to 1/4 corner.
-16 north drove iron stake N & L 19.96 1/8 (1317.44
-16 east of above 1/16 drove iron stake N & L 19.96 5/16 (1317.52
on N-S 1/16 line.

6-1910 Ch Larson S 128 B. S 32. H Lake.
found gaspipe with iron bolt.
-16 west temp point N & L 19.91 (13 14.06
-16 north found iron stake & chs N & lime filled hole refilled lime hole.
-16 center SE ~~cor~~ 1/4 32 set iron stake in lime hole.
19.92 (1314.72 east and 19.96 N. (1317.36 to corners.

1935 Co Hwy Dept. Book 78 found iron pipe & bolt.

2-1947 J Kerr B 32 P 62 24 Kalmar. fol this board.
no desc 4 corner - meas 2613.54 to 1/4 4-5 Kalmar a
stone found from B tree near stone which was lying at angle RPS 6/4/45

#853305 (2)

Card # 2. section corner S 32-33 New Haven
N 4-5 Kalmar.

11-1916 J Kerr P 260 B S 4-5 line between.
E Searles, C & A Carlson, Town Board of Kalmar.
found iron stake and bolt described in previous survey.
Meas south. set 1/16 iron & glass at 1305.93
chen stone at 1310.52 as 1/4 corner. on line
8" pin oak. S 50° 30' W 11.6'
16" " " S 23° 45' E 7.5'
also stake south of 1/4 4-5 1310.52 chen
1310.52 to south section corner 4-5 undescribed.
over.

1/4 4-5 now 3/8" x 26" rod in dry wash. B 32 P62 1947.
RPS 1947 - 60 Dm 14" pin oak S 23°45 E 8.0'
60 Dm 18" elm east 8.0'
distances from south 32-33. New Haven. south.
1916 - 1305.93 and 1310.52. or 2616.45 1947.261357
1916 1/4 4-5 south 2621.04 1947.2618.4

1935 CHO Complete on B 78. P4 - P75'
found. iron stake 1317.4 south of road alignment. P4.
P75 found iron pipe & bolt. -
Willow. east 27.3 - willow LE 60.6
Meas North to fence east W1/4 32. 2634.8 - set nail as
1/16 N & L. 1317.4 which came in center road. as 1/16 corner
between W1/4 33 (nothing set, dug for corner) and SW cor 33

#853305 (3)

Card # 3 S32-33 New Haven 108-15

N 4-5 Kalmar 107-15

6-19-1970 Co surv. found 1¼" x 33" old pipe and ⅞" x 24" bridge bolt with large burr on end. set C/M over bridge bolt - C/M down 6"+ with glass etc.

- 20 D in hub on N side large willow just Sf fence E 85.22.
- bottle cap in power pole # 22726. 1' Sf W 26.8
- cope bottle cap in top of corner fence post each 37.0
- corner lies in line fence each slightly South .5'
  " " " " " West " " 1.0'
  " " 4'+ west center traveled road
  field low on each side, high on west side (over)

-16 south found large round headed iron down 18" set in P260B 1916 by JKerr at 1303,8 R 1305.93.
corner came exact line fence east 4'+ west Center traveled road

- center power pole # 22734 NNW 152.5
- center large corner post east 36.4.

Also found new ½" rod & 3rd nail 1.2 E and 3.25 S. pulled this rod.
- pushed line south and mused 3/8" rod placed as ¼ 45 in 1947 by about .2' on east side rod, line from 1/16 south meas by Sanders crew. R 1310.52 in 1916 (meas indefinate poor chainmen about ~~1310.4~~ 1308.9?
- to help locate section corner meas from north; found pipe in blacktop road at 1318.1

Feb., 1863 P.C. Compton Pg. 68 No. 95 Section Post Gone - Established it by U.S. Field Notes From Witness trees, used in S.W. ¼ sec. 33 Survey

Section corner South 32-33 New Haven 108-15
North 4-5 Kirkman 107-15

#853305

Cook Notes

80.00 Set post corner 10 Brothers 4-5-32-33
White Oak 20 N 10° E 32
Black Oak 10 N 45° W 68
White Oak 14 D 80° W 25
Black Oak 24 D 51° E 45

"853305" S SEC COR 32-33 10S-15 7-23-79 ER MC
FOUND CIM IN GOOD CONDITION DOWN 0.9'
IN CR 105. CORNER FALLS 4' W OF ℄ CR 105
& IN LINE FENCE EAST & FENCE ROW WEST.