Certificate of Location of Government Corner

ID#: 420308 **Description:** N 1/4 SEC COR 3 42 **Date Set:** 8/30/1979 **County:** Fillmore

Section: 03 **Township:** 104N **Range:** 12W **Monument Description:** 5/8" iron rod

Reference Ties:

The corner falls 4' west of centerline of twp road south and 1' south of centerline of CR 138
County Survey Disk in PP #43020 SE 48.51'
County Survey Disk in CP NNE 46.64'
Olmsted County corner "523405" E 17.2'
This corner is located by GPS reference stations "MG & Jack"

Corner History:

11-1895 O.H. Case, Fillmore County Surveyor, set a 1 1/2" x 2 1/2" x 30" solid iron bar for the corner during a survey of Section 3, T104N, R12W.

8-13-1979 Olmsted County Surveyor dug with backhoe and found O.H. Cases 1 1/2"x2 1/2"x30" iron lying flat 4' deep beneath road. Found the mark where iron had stood and drove iron down through the mark. Set spike at road surface.

8-30-1979 Olmsted County Surveyor set 5/8" iron rod in place of spike set 8-13-79

2-4-1994 Dave Knutson, Fillmore County Surveyor, prepared a section corner certificate which showed the Olmsted County 5/8" iron rod at the corner. The certificate also matches the Olmsted County reference ties. Fillmore County Certificate of Location Doc. No. 373484

5-21-2009 Olmsted County survey crew found a 5/8" pipe down 0.2' in good condition. The source of this pipe is unknown. The pipe does not fit the ties which indicate the pipe is 1.2' east of the correct location. Removed the pipe.

5-27-2011 Olmsted County survey crew found 5/8" rod leaning east. Reset in plumb position using reference ties.