Certificate of Location of Government Corner

ID#: 430107 **Description:** N SEC COR 1 2 43 **Date Set:** 6/2/1981 **County:** Fillmore

Section: 01 **Township:** 104N **Range:** 13W **Monument Description:** 1" square pipe

Reference Ties:

The monument is down 0.7'
The corner falls in centerline of E-W road and in line with fence south
Spike in top of CP SSW 36.8'
This corner is located by GPS measurement

Corner History:

1853 Gov't Notes Phipps and Fitzgerald, Deputy Surveyors; North between sections 1 & 2. 78.2 chs. Intersect North boundary 250 links west of corners and set a stone 15" long 10 broad and 4 thick for corner to sections 1 & 2.

8-1893 William Fraser, Surveyor, (Bk.A Pg.530 No.494) looked for this corner, but couldn't find it.

6-2-1981 Olmsted County Surveyor dug and found Gov't stone shattered, but put together to form 4x10x10. Put RR spikes on the north and south sides of the stone and set a 1" square pipe at the road surface over the stone. This corner is 166.09 W'ly of the S 1/4 corner 35 found 6-4-1981. See Fillmore County Certificate of Location Doc. No. 374609

11-1-2010 Olmsted County survey crew found 1" square pipe at surface with top damaged and bent/leaning westerly. Excavated down to the point where the pipe was straight and cut off the top 0.6'. Pipe is down 0.7' with no cap.