Certificate of Location of Government Corner

ID#: 430307 **Description:** N SEC COR 3 4 43 **Date Set:** **County:** Fillmore

Section: 03 **Township:** 104N **Range:** 13W **Monument Description:** 2-1/2" square iron bar

Reference Ties:

The corner falls 1-1/2' north of east-west fence and 51' WNW of centerline of Fillmore/Olmsted CSAH 1
The monument is up 0.1'
This corner is located by GPS measurement

Corner History:

11-5-1853 Charles Phipps and Edward Fitzpatrick, Deputy Surveyors, measured north 77.40 chains, between Sections 3 and 4, for subdivision of Sumner Township. Intersected standard parallel 218 links (143.88') west of corner. Set 3"x11"x17" stone.

Date unknown O.H. Case, Fillmore County Surveyor (from 1894 thru 1912), set 2-1/2"x2-1/2"x30" solid iron bar for the corner.

11-9-1984 David Knutson, Fillmore County Surveyor, found 2-1/2"x2-1/2"x30" solid iron bar at surface in good condition. The iron bar is typical of those monuments set by O.H. Case from 1894 thru about 1912. The corner falls 1-1/2' north of east-west fence. Fillmore County Certificate of Location Doc. No. 374611. RPs - Blue Tie in north side of fence post W 10.16', Blue Tie in south side of fence post ESE 3.82', Concrete nail in centerline of CSAH 1 E 55.60'.

11-14-1984 Olmsted County Survey Crew found 2-1/2" square iron bar at surface. The corner falls 1-1/2' north of east-west fence. McGhie & Betts pipe 0.85' south and 1.04' east of iron.

10-28-2010 Olmsted County Survey Crew found 2-1/2" square iron bar up 0.1' in good condition and measured its position using GPS.

7-2011 Jeff Brand, Fillmore County Surveyor, found 2-1/2" square iron bar in good condition and measured its position using GPS.

7-2011 Jeff Brand, Fillmore County Surveyor, computed a new corner location on the standard parallel by intersecting the west line of the Northwest Quarter of Section 3, T104N, R13W with the south line of Southwest Quarter of Section 33, T105N, R13W. The new corner location falls 0.48' south of the existing 2-1/2" square iron bar.