Certificate of Location of Government Corner

ID#: 440109 **Description:** SEC CEN 1 44 **Date Set:** 5/1/1902 **County:** Olmsted

Section: 01 **Township:** 104N **Range:** 14W **Monument Description:** Note: Information regarding this center of section is provided for reference purposes only. A professional land surveyor should make the decision whether to use any existing survey monument or the computed intersection of quarter lines.

County Surveyor recommends using the computed intersection of quarter lines for the center of section.

2"x4" topped stone

Reference Ties:

The corner falls 2' west of fence south, 12' south of east-west fence and 25' east fence north
Channel iron post 1/2' east
Knot on SW side top of corner post WNW 27.7'
This corner is located by GPS reference stations "Hoffman C & D"

Corner History:

5-1-1902 William Fraser, County Surveyor, (Book B, Pages 16-17) found stake under boulder at intersecting quarter lines set by Mr. Freeman in a previous survey. 1/16th North set 6"x8"x22" stone on line at government proportionate measure of 19.90-1/2 chains (1313.73') then 18.31-1/2 chains (1208.79') to North 1/4. 1/16th East set 3"x5"x15" stone midway and on line to East 1/4. 1/16th West set 6"x8"x20" stone midway and on line to West 1/4. 1/16th Center of NE 1/4 set corner at intersecting sixteenth lines. 1/16th Center of NW 1/4 set stone at intersecting sixteenth lines.

9-16-1971 Roger Brand, County Surveyor, found stone. RPs - Knot on SW side top of corner post WNW 27.7', Concrete nail in knot west side fence post North 10.05'. Set channel iron post 1/2' east. 1/16th North found 6"x8"x22" stone down 0.8' with large stake on west side. Set cross shaped iron on east side.

11-12-1971 Roger Brand, County Surveyor, 1/16th West found 6"x8"x20" stone. 1/16th East set 1-1/4" pipe.

5-3-1995 County Survey Crew found stone down 0.8' with channel post on east side.

5-15-1995 County Survey Crew 1/16th East found 1-1/4" pipe up 1' with steel post beside it. The corner falls 9' south of east-west electric fence line.

10-10-2007 County Survey Crew found 2"x4" topped stone down 1.3' in good condition and measured its postion using GPS.

3-11-2011 Joel Thoreson, County Surveyor, recommends using the computed intersection of quarter lines for the center of section. Based on the county's section breakdown, the 2"x4" topped stone, as located by GPS in 2007, falls 0.23' south and 0.03' west of the computed center.