Certificate of Location of Government Corner

ID#:440206 **Description:** 1/4 SEC COR 2 3 44 **Date Set:** 1/18/2002 **County:** Olmsted

Section: 02 **Township:** 104N **Range:** 14W **Monument Description:** 1" square pipe w/cap RLS #15809

Reference Ties:

The corner falls 8' east of centerline of TH 63 on curve
County Survey Disk in PP ENE 66.34'
County Survey Disk in transformer PP SSE 190.95'
This corner is located by GPS measurement

Corner History:

1853 Gov't Notes North on true line between sections 2 and 3. 40.00 chs. Set quarter section post. Blk. Oak 12 in. S3°W 177 lks. Br. Oak 8. In. S40°W 135 lks.

4-1875 Thomas Hunter, (P. 271 No. 269), County Surveyor, states corner gone, but stumps of both bearing trees plainly marked. Reset corner with 8"x10"x15" boulder stone.

1-1902 William Fraser (P. 29 Book B), County Surveyor, found stone.

1945 Jerry Blake, Frank Eaton, Surveyors for county highway department; E 1/4 corner gone by road work. Found stone with cross 990' north of corner 8x8x24 with cross.

8-5-1974 County Surveyor set a 1 1/4" pipe in bit. Surface of TH 63-8' east of center line. Highway construction destroyed all possibilities of the corner being found. Set the corner by projecting the line from the north over an 8" square stone which is 990' north of the 1/4 corner. RPs- CSD in PP ENE 66.34', CSD in transformer PP SSE 190.95'

11-13-2001 County Surveyor found 1 1/4" square pipe down 0.6'. Pipe is split on one side.

1-18-2002 County Surveyor removed 1 1/4" square pipe and set 1" square pipe w/cap at surface.