Certificate of Location of Government Corner

ID#: 440207 **Description:** N SEC COR 2 3 44 **Date Set:** 1/15/2002 **County:** Olmsted

Section: 02 **Township:** 104N **Range:** 14W **Monument Description:** 1" square pipe w/cap RLS #15809

Reference Ties:

The corner falls 1' south of centerline of CSAH 6, in centerline of twp road south and 2.4' north of center of manhole
County Survey Disk in PP SE 50.38'
60d spike in N side Evergreen SW 52.5'
This corner is located by GPS measurement

Corner History:

1853 Gov't Notes No Dep. Sur. Noted 78.60 Intersected standard parallel 279 lks. West of south quarter corner of section 34. Set post. Br. Oak 10 in. S86°W 443 lks. White Oak 12 in. S15°E 444 lks.

9-1853 Gov't Notes on S 1/4 corner Sec. 34 of Township 105 North of Range 14 West. West on south boundary of section 34. 40.00 Est quarter section post with trench. Br. Oak 10 in. N81°E 235 lks. Thomas Hunter explains above incorrect Gov't chainage between N Sec. Corner 2-3 and S 1/4 corner Sec. 34 in Survey No. 341 P. 348.

4-1875 Thomas Hunter (Book A, P. 271 No. 269), County Surveyor, found remains of old stake in center road which checked with SE bearing tree still standing. Set a boulder 6"x10"x16" in its place. Meas. E to S 1/4 corner Sec. 34=5.46 chs.

5-1878 Thomas Hunter (Field Book 5, Page 67, unrecorded) found stone set.

6-1892 Thomas Fraser (P. 487 No. 413), County Surveyor, used corner to reset S 1/4 corner Sec. 34 (No description of corner.) by Gov't meas. Of 5.63 chs.

10-10-1898 W. Fraser found and used stone monument for Brin's Plat.

1-1902 William Fraser (P. 29 Book B), County Surveyor, found boulder.

5-1902 William Fraser (Book B, Page 16) found stone as corner. Meas. E to S 1/4 corner Sec. 34=5.47 chs.

7-24-1974 County Surveyor dug with backhoe and found a boulder 7"x10"x15" ± 2.2' deep and approx. 3' south of the centerline of CR 6. Set a CIM over the stone with a 1" pipe on the north side of the stone.

11-06-2001 County survey crew found corner gone due to new construction.

1-14-2002 County survey crew set pk nail at surface from 1992 Yaggy Colby traverse data.

1-15-2002 County survey crew set 1" square pipe w/cap at surface.

3-18-2004 County survey crew found 1" square pipe w/broken cap at surface in good condition. Replaced cap.

7-2-2007 County survey crew found 1" square pipe w/cap broken. Drilled out cap, lowered pipe and set new cap in pipe.