Certificate of Location of Government Corner

ID#:440304 **Description:** 1/4 SEC COR 3 10 44 **Date Set:** 7/30/1974 **County:** Olmsted

Section: 03 **Township:** 104N **Range:** 14W **Monument Description:** Cast Iron Monument

Reference Ties:

The corner falls 3' south of centerline of E-W twp road
County highway disk in SW side 20" Oak NE 34.94'
Spike in W side 10" Oak SSE 46.14'
Center of easterly of Twin 18" Oaks SW 31'
County Survey Disk in PP #10670 NNW 34.34'
This corner is located by GPS measurement

Corner History:

1853 Gov't Notes No Dep. Sur. Noted West on true line between sections 3 and 10. 40.00 chs. Set quarter section post. Br. Oak 14 in. S69 1/4°E 321 lks. Br. Oak 13 in. N10 & 3/4°E 400 lks. 80.00 chs. To section corner.

4-1875 T. Hunter (P. 271 No. 269), County Surveyor, found stake in center of road, both bearing trees standing, found stake correct as placed, set a stone in its place.

11-1966 Sankstone & Assoc. found 8" diameter stone. RPs- disc in 42" maple N 58.40', disc in 24" burr oak NE 35.07', disc in 6" burr oak SE 39.72', disc in corner fence post N 36.29'.

7-30-1974 Olmsted County Surveyor dug in area and scrapped subsoil to prove corner. Accepted Sankstone location for the corner since it fits the measurements and lines of occupation. Reset a CIM over a 1/2"x24" rod.

10-8-1984 Olmsted County Surveyor found CIM (down 4") ± 3' South of centerline E-W road.

11-09-2001 Olmsted County Surveyor found CIM down 0.5' in good condition.