Certificate of Location of Government Corner

ID#:440405 **Description:** SEC COR 4 5 8 9 44 **Date Set:** 8/8/1974 **County:** Olmsted

Section: 04 **Township:** 104N **Range:** 14W **Monument Description:** Cast Iron Monument

Reference Ties:

The corner falls 7' north of centerline of E-W twp road and 6' east of centerline of N-S twp road
County Survey Disk in SE side PP #10634 NE 35.45'
County Survey Disk in W side 28" Oak SSE 117.37'
Top center TCM box SW 53.91'
Punch hole in S end 15" CMP SW 47.45'
Punch hole in N end 15" CMP WNW 43.25'
This corner is located by GPS measurement

Corner History:

1853 Gov't Notes North between sections 8 and 9. 80.00 chs. Set section post. Burr Oak 6 in. ?42 1/4°E 358 lks. Burr Oak 7 in. S44 & 3/4°W 585 lks. Burr Oak 5 in. N36 & 3/4°E 453 lks.

5-1878 Thomas Hunter, County Surveyor, states corner missing, no evidence of corner after digging over a large span, and all bearing trees gone. Found line of old fence running east avered by all settlers as set from original corner before road opened running east. Also, avered north and south road fences just 2 rods from corner. Set a stake well down at this point.

8-8-1974 Olmsted County Surveyor dug with tractor and found a very definite and deep stake hole in subsoil. There was also an old wooden culvert buried in the area of the corner. Put an iron rod in the hole and set a CIM over. Corner falls in NE corner of the intersection. RPs- CSD on SW side PP #10634 NE 35.45', Center tele box SW 53.9', spike & CSD on west side 24" oak SSE 117.4', Corner was 5' deep & falls in the NE corner of the intersection.

5-18-1995 Olmsted County Surveyor found CIM down 0.4' in good condition.

11-06-2001 Olmsted County Surveyor found CIM down 0.4' in good condition.