Certificate of Location of Government Corner

ID#: 440407 **Description:** N SEC COR 4 5 44 **Date Set:** 6/28/1971 **County:** Olmsted

Section: 04 **Township:** 104N **Range:** 14W **Monument Description:** Cast Iron Monument

Reference Ties:

The corner falls 2 1/2' north of centerline of twp road west and 15 1/2' west of centerline twp road south
Minnesota Highway Disk in E side PP #11017 SSW 122.8'
Concrete nail in SW side PP #4018 NW 30.72'
20d nail in S side 36" Oak WNW 78.00'
This corner is located by GPS measurement

Corner History:

1853 Gov't Notes Ball, North between sections 4 & 5; 79.38 intersected north boundary line 410 lks west of 1/4 section post south of section 32. Set post. RPs- 8" burr oak N88 E 59 links, 10" black oak S72E 893 links.

5-10-1878 T. Hunter (Book A, Pg. 343, No. 337) found the remains of the old stake and set a new stone 3" by 6" by 14" with glass and pottery around it.

4-23-1906 Charles Armstrong (Book B, Pg.104) Found stone and pottery. Meas. East and found stone boulder, meas. 16 south and set stone.

8-25-1931 County Highway Department Bk.61 Pg.7; controversy corner-assumed. Assumed corner could be East 9.84'.

10-18-1940 County Highway Department B.112 Pg.3 Assumed corner 5/8" rod set. RPs- center Geo BM which lies 3' s of 24" elm N 30.83', soike in corner fence post SW 41.45', disc in 24" oak, last oak on west end WNW 87.9'. Note: correct corner west ± 10' & 2' north.

6-28-1971 County Surveyor found the stone with witness pottery. Set cast iron monument over 5/8" rod and stone.

Note: this corner as found is correct corner. A corner (3/4" iron rod) was set and used by county highway department, M.H.D. and others for many years. Old corner rod was ± 10' East and ± 6' South of correct corner.

11-6-2001 County survey crew found CIM down 0.9' in good condition.

1-4-2006 County survey crew found CIM down 0.9' in good condition.

7-2-2007 County survey crew found CIM down 0.9' in good condition.