Certificate of Location of Government Corner

ID#:440506 **Description:** 1/4 SEC COR 5 6 44 **Date Set:** 12/28/2004 **County:** Olmsted

Section: 05 **Township:** 104N **Range:** 14W **Monument Description:** 1" square pipe w/cap RLS #15809

Reference Ties:

The corner falls in centerline of CSAH 6 and 28 1/2' west of centerline of CSAH 8
County Survey Disk in NE side PP SE 81.25'
This corner is located by GPS measurement

Corner History:

1853 Gov't Notes Ball; North between sections 5 & 6 40.0 set 1/4 section post. RPs- 10" burr oak N65E 91 links, 7" burr oak S70W 97 links.

6-1878 T. Hunter Pg.348 No.341; Corner gone and all bearing trees gone. Set boulder 10x15x30.

1925 county highway department Bk.38 Pg.89 shows stone.

5-1940 county highway department; 3/4" rod over stone monument. RPs- disc tele pole SW 50.95', disc corner fence post E 33.45'. NO GOOD

5-1950 J. Kerr Bk.46 Pg.72; Used E 1/4 & W 1/4 section 5 to lay out property with angles south as fences. Set property corners.

1960 DuVall MHD; Found stone. RPs- disc tele pole NE 41.2', disc tele pole SE 42.3', disc pp NW 46.6'. NO GOOD

1964 county highway department Bk.290; 3/4" rod. RPs- disc in tree NE 84.4', disc TP WNW 61.9', disc PP SE 42.67' SW 68.3', disc TP NNW 101.3', disc corner fence post NE 46.55'. NO GOOD

10-1972 County Surveyor set CIM over 5/8"x12" iron.

7-5-1996 County Surveyor found CIM in good condition 2" below surface of CR 6. RPs- CSD in east side TCM post NW 31.66', Punch mark in top pipe corner post NE 88.53', CSD in PP #45427 SE 66.20'.

5-14-2003 County Surveyor referenced location, removed CIM.

12-28-2004 County Surveyor set 1" square pipe w/cap at surface from 2003 regrade tie-out.

9-27-2007 County Surveyor found 1" square pipe w/cap at surface in good condition.