Certificate of Location of Government Corner

ID#:440507 **Description:** N SEC COR 5 6 44 **Date Set:** 3/7/2005 **County:** Olmsted

Section: 05 **Township:** 104N **Range:** 14W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The corner falls 21' north of centerline of E-W twp road and 37 1/2' west of centerline of residential driveway north
Bottle cap in PP #6810 WNW 40.82'
County Survey Disk in PP NE 73.50'
Post w/sign 2' north
This corner is located by GPS measurement

Corner History:

1853 Gov't Notes, Ball; North between sections 5 & 6 78.07 intesected north boundary line 440 links west of 1/4 section post to south section 31. Set post. RPs- 12" burr oak S25E 133 links, 8" burr oak S53W 231 links.

6-1878 T. Hunter Pg. 348 No. 341 Corner in dispute many years. Mr.N Lyon avers that he was present and saw the Deputy Surveyor when he made the correctiond and that he was with the surveyor when he set this corner at "A" and that he has often times since seen it and that the stake found with witness tree is where it was set in record. The SW witness tree has been cut and grubbed out.

1938 J. Kerr Bk.12 Pg.16; Found hole where stake was and drove iron stake in hole. Set wood stake by its side & piled rock around it. RPs- Nail NE pin oak 29.5', Nail S of E to twin burr oak stump 61.5'. NO GOOD

6-1971 County Surveyor found true S 1/4 31 set by W. Fraser 1897 and found by Kerr in 1939 set CIM over same. RPs- 10' north centerline road running west some 18" north, north edge road, 49.55' SE to center seam west end conc. Culvert, 66.2' SW center tele pole up 4'.

10-1972 County Surveyor set 5/8"x3' rod .

11-2-1998 County Surveyor found 5/8" iron.

2-25-2005 County Surveyor found 5/8" rerod down 0.2' in good condition.

3-7-2005 County Surveyor removed 5/8" rerod and set 4' telspar pipe w/cast iron cap at surface driven to refusal. Set post w/sign.

9-21-2007 County Surveyor found cast iron cap on telspar pipe up 0.1' in good condition.