Certificate of Location of Government Corner

ID#:440604 **Description:** 1/4 SEC COR 6 7 44 **Date Set:** 9/28/2007 **County:** Olmsted

Section: 06 **Township:** 104N **Range:** 14W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The corner falls 1' west of centerline of N-S twp road, in line with fence west and 28' north of centerline of field entrance east
Cross in N end 18" RCP ESE 33.70'
Cross in S end 18" RCP SE 48.87'
This corner is located by GPS measurement

Corner History:

1853 Gov't Notes, Ball; East on true line between sections 6 & 7 40.3 set 1/4 section post. RPs- 10" burr oak S9 1/4E 105 links, 8" burr oak N22E 128 links.

6-1878 T. Hunter Pg.348 No.3341; Corner missing, but NE bearing tree standing and SE bearing tree stump in place. Reset stake.

1927 Olmsted county highway department Bk.48 Pg.17 found stake above stone. RPs- 80D in 18" oak WSW 35.0', 80d in TP NW 49.8'.

10-3-1940 J. Kerr found tile and concrete monument. Set with 3/4" iron bar riser. RPs-80D nail on SE side of 18" Oak West SW 34.5'. Spike and Disc in corner F.P. West 43.5 ft. 2"x2" hub in fence line SSW 98.25'.

10-24-1972 Olmsted County Surveyor reset the corner with a temp 3/4" x 4" rod using the notes and as near as possible the witness tree taken by Ch. Armstrong Rp's nail in NE corner of the Ch. Armstrong Br. Tree 4' S. of W 30.3'.

6-28-2000 Olmsted County Surveyor found 3/4" rod 0.4' in good condition.

9-28-2007 Olmsted County Surveyor found 3/4" rerod at surface bent. Removed 3/4" rerod and set 5' telspar pipe w/cast iron cap down 0.4'.