Certificate of Location of Government Corner

ID#:440606 **Description:** W 1/4 SEC COR 6 44 **Date Set:** 3/29/2005 **County:** Olmsted

Section: 06 **Township:** 104N **Range:** 14W **Monument Description:** 1" square pipe w/cap RLS #15809

Reference Ties:

The corner falls in centerline of CSAH 6 and 15' west of centerline of driveway north
County Survey Disk in NNE side PP NW 111.47'
This corner is located by GPS measurement

Corner History:

7-1853 Gov't Notes John Ball, Deputy Surveyor Township 104 North between Ranges 14 and 15 West North between sections 1 and 6. 40.00 chs. Set quarter section post. Black Oak 6 in. N71°E 43 lks. Burr Oak 10 in. S52°E 103 lks. 44.30 chs. Stream 50 lks wide runs East. 78.24 chs. Intersect 1st Standard parallel 450 links West of 1/4 Sec. Corner to Section 36 of T105N Range 15W and set post corner to Range 14 and 15 of Township 104 North.

6-4 & 5-1878 Thomas Hunter, County Surveyor, (Bk. A, Page 348, No. 341 and old Field Bk. 5, P. 73 & 74) states: "1/4 post missing and witness trees gone and as no evidence of it was to be found or forthcoming, we set it on line and the proper distance according to the field notes." Measured 40.03 chains to the S.W. Corner 6 and 38.27' chains to the N.W. Corner 6. He also states: "in setting stake at D (W. 1/4 corner 6) we found and old stake within a few inches of our own said to have been set by Mr. Freeman, a surveyor, who established this 1/4 post in a similar manner." He used this corner to set the 1/16th North (a stake), the 1/16th East (a 22" x 10" x 3" stone), and the Center 6 (a 18" x 8" x 2" stone).

6-7-10-1878 Thomas Hunter (Bk. A, Page 350, No. 342 and Old Field Book 5, page 75) found corner as desccribed in Survey No. 341. He used this corner to set the Center 1 (an 18" x 8" x 5" boulder stone in the center of the road) at intersecting.

6-1885 T. Hunter Pg.398 No.388; Found stake. 16 west set boulder stone, and meas. South.

4-1911 Charles Larson Og.156B; Found corner in road. 16 east set point.

5-1940 county highway department; Assumed corner. 3/4" iron rod. 1 1/2" pipe N 33.05', 1 1/2" pipe S33.0', hub NE 88.9', hub NW 100.1'. Corner reset by line from center 6.

5-1979 County Surveyor set CIM over 1/2"x17" rod. Corner is 3.75' east of rod set in 1971 and is 1' north of centerline E-W road.

5-14-2003 County Surveyor referenced location, removed 15" CIM, found 1/2" iron rod down 1.8'. Left iron to be destroyed during road regrade.

3-29-2005 County Surveyor set 1" square pipe w/cap at surface from reference angle. CSD with concrete nail in NNE side of pp (no #) NW 111.47'. Monument falls in centerline of CR 6 and 15' west of centerline of driveway north.

9-27-2007 County Surveyor found 1" square pipe w/cap at surface in good condition.