Certificate of Location of Government Corner

ID#: 440608 **Description:** N 1/4 SEC COR 6 44 **Date Set:** 10/31/2000 **County:** Olmsted

Section: 06 **Township:** 104N **Range:** 14W **Monument Description:** Cast Iron Monument

Reference Ties:

The corner falls 2' south of centerline of E-W twp road and 76' east of centerline of residential driveway south
Hard nail in E side 16" Cedar NNE 93.4'
Punch mark in E end 12" CMP NW 45.1'
County Survey Disk in PP WNW 64.87'
Property corner pin S 33.00'
SE corner of mobile home NNE 93.90'
This corner is located by GPS reference stations "Elman & Hanken"

Corner History:

1878 T. Hunter (Book A, Pg. 348, No. 341) set a stake on line from S 1/4 corner of 36-105-15 and SE corner Section 36-105-15 and at gov't prorated distance from the NE corner Section 6-104-14 to NW corner Section 6-104-14.

4-1911 C. Larson (Book B, Pg. 156) set a stake.

12-1930 J. Kerr (Book 4 Pg. 63) set a limestone 443.5' west of the township corner on straight line.

6-29-1971 County Surveyor dug and found the limestone set by J. Kerr. Set CIM over stone.

10-26-1984 County Surveyor found CIM it appears to lean SE'ly and tie to pole WNW 0.15' long. Did not have time to straighten.

11-2-1998 County Survey crew found CIM leaning South. Dug out CIM and reset over stone.

10-31-2000 County Survey crew found CIM down 0.3' with head broken off and leaning. Set CIM over stone down 0.4'.

1-29-2013 County Surveyor computed a new corner location on the standard parallel by intersecting the n-s quarter line of section 6 with the south line of section 36-105-15. The computed position is 0.02' south of the inplace cast iron monument.