Certificate of Location of Government Corner

ID#:450106 **Description:** 1/4 SEC COR 1 2 45 **Date Set:** 3/29/2005 **County:** Olmsted

Section: 01 **Township:** 104N **Range:** 15W **Monument Description:** 1" square pipe w/cap RLS #15809

Reference Ties:

The corner falls 1 1/2' north of centerline of CSAH 6 and 7' east of centerline of twp road south
County Survey Disk in E side 12" Oak NNE 62.30'
County Survey Disk in NE side PP SE 64.19'
This corner is located by GPS measurement

Corner History:

1853 Gov't Notes, John Ball; Set a section post. RPs- 12" black oak N52 E400 links, 10" black oak S10 1/2 E 285 links.
Gov't Notes, John Quigley, Deputy Surveyor; North on true line between sections 1 & 2, 5.60 chs creek 75 links wide runs NE. 40.0 chs set 1/4 section post. RPs-12" black oak N52 E400 links, 10" black oak S10 1/2 E 285 links. 78.10 chs intersected 1st standard parrallel 490 links, west of 1/4 section corner on south boundary of 16" burr oak S77°W 255 links, 14" elm N84°E 256 links.

6-1877 T. Hunter Pg.320 No.314; Corner gone, NE bt gone and SE bt a stump avered by Mr. L.Shipper as used by surveyors as bearing tree and has memory of marks on tree. This would make meas. North 1/4 corner 3 rods long. Reset stake from field notes using this stump.

6-1878 T. Hunter Pg.305 No.342; Corner gone, all trees & stumps now gone. Controversy among settlers as to location. Compromise reached and stake set very near original location. 16' E set stake, 16' N set temp stake, 16' center NW 1/4 set stake.

6-1895 W. Fraser, Pg.637 No.574; Stake gone. Found center section 1 and 1/16 corner between center & W 1/4 stakes set by Hunter Pg.350. Run this line & meas carefully and drove gas pipe 4' long well down. 16 west set stone.

8-1925 county highway department Bk.38 Pg.83; Shows iron pipe over stone monument.

5-1940 county highway department Bk.109 Pg.76; Found pipe. Set 3/4" rod riser on west side pink hardhead. 1 1/2" pipe N 33.15'.

5-17-1979 County Surveyor found a 3/4" rod in blacktop and approx. 1' south of this and under blacktop found a 3/4" rod which fit the remaining county highway department RP's.

5-24-1979 County Surveyor found a 1 3/4" O.D. pipe in the old road 3' deep. There was a wood stake in the top of the pipe, but the recorded boulder was gone. Drove a 3/4"x38" iron in the top of the pipe.

6-7-1979 County Surveyor set a CIM over the pipe found 5-24-1979. RPs- 2" pipe on east side fence north and 4' north corner post north 32.96', CIM 8' north centerline E-W road and 7' east centerline road south, punch hole west end CMP SW 47.88'.

5-14-2003 County Surveyor referenced location, removed 15" CIM, found 1/2" iron rod down 2.1'. Left iron rod to be destroyed by road regrade.

3-29-2005 County Surveyor set 1" square pipe w/cap at surface from reference angle. CSD with concrete nail in NE side of PP (no #) SE 64.19' and CSD with concrete nail in east side of 12" Oak NNE 62.30'. Monument falls 1 1/2' north of centerline of CR 6, 7' east of centerline of twp road south and in line with fence north.

4-29-2009 County Surveyor found 1" square pipe w/cap RLS #15809 at surface in good condition.