Certificate of Location of Government Corner

ID#:450109 **Description:** SEC CEN 1 45 **Date Set:** 3/29/2005 **County:** Olmsted

Section: 01 **Township:** 104N **Range:** 15W **Monument Description:** Note: Information regarding this center of section is provided for reference purposes only. A professional land surveyor should make the decision whether to use any existing survey monument or the computed intersection of quarter lines.
1" square pipe w/cap RLS #15809

Reference Ties:

The corner falls in centerline of CSAH 6 and 4' west of fence line south
This corner is located by GPS measurement

Corner History:

6-7-1878 T. Hunter Pg.350 No.342; Set boulder setone 5x8x18. 16 west set, 16 center NW 1/4 S1 set stake, 16 north set stake.

6-17-1885 T. Hunter Pg.398 No.388; Found boulder stone in center of road. Set witness stakes 50 links north and south of corner. 16 east set boulder stone.

1925 county highway department Bk.38 Pg.83; Shows mon. Inp. At center 1.

5-1940 county highway department found boulder, Set 1/2" rod and stake riser. RPs- spike 18" oak ESE 69.3, spike 15" maple SSE 87.3, 3/4" iron S 33.0, 3/4" iron N 33.0, hub S 68.25, hub N 64.4.

5-24-1979 County Surveyor found 1/2" rod and hub over boulder 1' S of centerline and 2 1/2' west of the line of the fence south.

5-31-1979 County Surveyor found boulder at the center 1 is south of the E-W 1/4 line section 1.

6-1-1979 County Surveyor dug at 1/16 west and found stones shattered. Removed stone and found stake hole. This corner came very near midway and on line between the boulder at the center 1 and the W 1/4 corner 1.

7-16-1979 McGhie's & Betts, Inc. set 5/8" pipe as center section 1 at intersecting 1/4 lines 6.4' north and .4' west of the boulder used by the county highway department as the center 1.

8-31-1992 R. Halverson set monument.

NOTE: We believe the E 1/4 corner 1 and the W 1/4 corner 1 have been reset very near the respective locations used by T.Hunter. Therefore, if the boulder at the center 1 and the stake hole at the 1/16 west are Hunter's monuments, at this time we conclude that Hunter errored certificates filed on the west,east, north, and south 1/4 corners of section 1.

5-14-2003 County Surveyor referenced location, removed pk nail.

3-29-2005 County Surveyor set 1" square pipe w/cap at surface from reference angle. Monument falls in centerline of CR 6 and 4' west of fence line south.

10-11-2006 W. Claassen Surveying found and used 1" square pipe w/cap.

12-6-2006 V. Fangman found and used 1" square pipe w/cap.

6-12-2007 V. Fangman found and used 1" square pipe w/cap.

4-29-2009 County Surveyor found 1" square pipe w/cap at surface in good condition.