Certificate of Location of Government Corner

ID#:450306 **Description:** 1/4 SEC COR 3 4 45 **Date Set:** 3/29/2005 **County:** Olmsted

Section: 03 **Township:** 104N **Range:** 15W **Monument Description:** 1" square pipe w/cap RLS #15809

Reference Ties:

The corner falls 1' north of centerline of CSAH 6 and 2 1/2' west of centerline of twp road south
County Survey Disk in NW side PP NE 62.07'
County Survey Disk in NE side PP SE 66.99'
This corner is located by GPS measurement

Corner History:

1853 Gov't Notes, Ball, north on true line between sections 3 & 4; 40.0 set 1/4 section post. Made mound with trench and drove charred stake in center and planted osage orange seeds in SE corner.

6-1877 T. Hunter Pg.319 No.313; Found stake in center road. Avered by settlers as original 1/4 post. Set boulder 6x8x16 in its place. 16 east set stake.

6-11-1878 T. Hunter Pg.351 No.343; Found stone Pg.319. Mr. Joyce avers corner once stood by post further south. Dug in that area & found post, but no stake. Left corner as is. 16 east set stake.

10-30-1895 W.Fraser Pg.584 No.533; Found corner set by Hunter. Replaced stake part of corner. 16 west found stake and planted limestone by its side.

1925 county highway department Bk.38 Pg.75; shows stone. 1/16 corner is a stone.

1935 county highway department Bk.75 Pg.78; found limestone with 2 1x2x18 survey stakes and an 80d spike on west side of stone. 1/16 west stone 2x6x18 west.

1940 county highway department Bk.109 Pg.5; Found stone. Placed 3/4"rod riser over stone monu. RPs- 1 1/2" pipe 33.0', spike in fence post N 63.6', spike in fence post SW 71.4', corner fence post SW 41.8'. 16 west placed conc. Monu. RPs- 1 1/2" pipe S50.0', 1 1/2" pipe N33.8', disc PP SE 49.02', disc in fence post S 47.56', hub SW 74.56', hub in fence S 60.69'.

1961 county highway department Bk.262; Conc monu as 1/16 between center 4 and 1/4 3-4 104-15. Spike & disc in PP SE 49.02', spike & disc in fence post S 47.56', hub in fence line S 49.08', hub in fence SW 70.02'.

6-1988 County Surveyor found 3/4' iron. Set 60d spike riser at surface of CR 6. Corner 1 1/2' N centerline CR 6 in line with fence north & 3' west of centerline twp road south.

5-14-2003 County Surveyor referenced location, removed 18" pipe w/cap, found 1/2" iron rod down 1.9'. Left iron to be destroyed by road regrade.

3-29-2005 County Surveyor set 1" square pipe w/cap at surface from reference angle. CSD with concrete nail in NW side of PP (no #) NE 62.07' and CSD with concrete nail in NE side of PP (no #) SE 66.99'. Monument falls 1.0' north of centerline of CR 6 and 2 1/2' west of centerline of twp road south.

4-29-2009 County Surveyor found 1" square pipe w/cap at surface in good condition.