Certificate of Location of Government Corner

ID#:450307 **Description:** N SEC COR 3 4 45 **Date Set:** 7/18/2002 **County:** Olmsted'

Section: 03 **Township:** 104N **Range:** 15W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The monument is at the surface
The corner falls 3' west of fence south and in line with E-W fence
Post w/sign 1' east
This corner is located by GPS reference stations "Aanestad A & B"

Corner History:

1853 Gov't Notes, Ball; 79.04 Intersected 1st Standard Parallel line 535 west of 1/4 section post on south boundary of section 33. RPs-20" burr oak S85 W203 links, 18" burr oak S81E216 links.

6-1877 T. Hunter Pg.319 No.313; B trees gone. Found stone in post hole avered by Mr. Gordy to be where original cor stood. Corner lies in line old fence south.

6-1878 T. Hunter Pg.351 No.343; Found stone as corner. 16 west set stake.

7-1893 W.Fraser Pg.521 No.487; Found stone with stake by its side. 16 west planted boulder stone.

1935 county highway department Bk.75 Pg.78; Found stone 2x4x18 on north side corner post 6".

11-15-1993 County Surveyor 1/16 west of N 3-4; Found stone set by WF, 8x12x18. Found stake on east side of stone about 12" o stake was remaining it seemed to be leaning. It was in \grassy area where old road ran @ one time. Left stone as is with iron on east side and short 3/4" rerod on west. It falls innline of brush row east.

11-19-1993 County Surveyor, we had probed & dug around corner post at an earlier time in this survey, but decided to look for other corners first. After finding the 1/16 west & section corner west also N 1/4 of 4 104-15 for distance, we dug at line & double dist.. Which comes 1 1/2' NW of 12"x10" square concrete corner post to fence E-W-S. There is concrete base out 2' around the post. This has been destroyed. Any sign of corner we dug in clay, but all was disturbed at corner location.

7-18-2002 County Surveyor set 6' telspar pipe w/Cast Iron Cap at surface on the line from South section corner 32-33, T105N, R15W to the South quarter corner section 33, T105N, R15W and at Thomas Hunters messure (306.90' in old field book 5 page 198 from said South quarter corner).

11-10-2011 County survey crew found cast iron cap in good condition