Certificate of Location of Government Corner

ID#:450409 **Description:** SEC CEN 4 45 **Date Set:** 6/9/2000 **County:** Olmsted

Section: 04 **Township:** 104N **Range:** 15W **Monument Description:** Note: Information regarding this center of section is provided for reference purposes only. A professional land surveyor should make the decision whether to use any existing survey monument or the computed intersection of quarter lines.
1" square pipe w/cap RLS #15809

Reference Ties:

The corner falls in centerline of CSAH 3 and 21 1/2' east of centerline of residential drive south
County highway disk in fence post NE 76.91'
County highway disk in fence post S 50.98'
County highway disk in fence post SE 63.80'
Ref pipe SSW 47.90'
This corner is located by GPS measurement

Corner History:

6-1878 T. Hunter Pg.351 No.343; Set stake. 16 west, east set stake.

10-1895 W.Fraser Pgt.584 No.533; Found stake. Set limestone 2x8x18 by its side. 16' west found stake. 16' east found stake.

1935 county highway department Bk.75 Pg.78; found pointed limestone 1.5' below surface of road. RPs- gate post SW 42.8', corner fence post south 31.9'. 1/16 corner east found 2'x6'x18' limestone in center of intersection of SAR # 6 and SAR #3. RPs- + in west headwall NW 42.4', + in east headwall NE 41.6'.

9-1936 Bk.79 Pg.1; 1/16 cor east of center 4 stone monu in place. RPs- fence post south 53.6', hub SE 58.0'.

1940 county highway department found stone and set 3/4" riser. 1/16 corner east found monument.

1964 J. Kerr Bk.283 set CIM over stone found. RPs- disc in fence post NE 76.91', disc in fence post S 50.98', disc in fence post SE 63.80'.

6-14-1988 County Surveyor found CIM. Set 60d spike riser at surface of CR #6

5-28-1999 County Surveyor found 60d spike riser set over CIM in good condition. CIM is down 1.2'. Set ref pipe and tied out corner.

6-9-2000 County Surveyor set 1" square pipe w/cap at surface from 1999 tie out.

12-16-2002 County Surveyor reviewed the location of this corner. Found that the monuments for this corner are not on the east-west quarter line but the stone at the 1/16th corner east is on the quarter line. Decided to use the computed center at intersecting quarter lines for Olmsted County Right of Way Plat No. 135.

10-14-2011 County survey crew found and removed 1" square pipe with cap in accordance with the 12-16-2002 decision.