Certificate of Location of Government Corner

ID#:450505 **Description:** SEC COR 5 6 7 8 45 **Date Set:** 6/9/2000 **County:** Olmsted

Section: 05 **Township:** 104N **Range:** 15W **Monument Description:** 1" square pipe w/cap RLS #15809

Reference Ties:

The corner falls 1 1/2' north of fence west, 3 1/2 east of centerline of CSAH 3 and 13 1/2' south of centerline of field drive west
Punched + in S end 18" CMP W 39.05'
Punched + in N end 18" CMP NW 49.52'
Ref pipe W 48.29'
This corner is located by GPS measurement

Corner History:

No governement notes recorded in Gov't Field Book.

6-1875 T. Hunter Pg.285 No.282; Found origianl corner. 16 north set stake.

6-1898 W.Fraser Pg.633 No.572; Found remains of SE BT, but not Hunter's stake. Found piece of gas pipe. Didn't set any corner. 16' north found Hunter's stake.

1940 Olmsted county highway department found 1 1/4" pipe monu. Set 3/4" rerod riser. RPs- Disc in 20" oak ENE 43.8', disc in fence post W 66.0', disc in TP SSE 89.6', 1 1/2" pipe W 35.0', 1 1/2" pipe E 33.0'.

1964 Olmsted county highway department Bk.283 Set CIM over pipe. RPs- hub in fence line SW 62.42', disc & hub in fence line SE 54.9'.

11-7-1978 Olmsted County Surveyor set CIM over a 3/4"x25" iron 3.30' east and 4.95' north of the pipe found as per W.Fraser's survey. Corner is 1 1/2' north of the fence west and 3 1/2 east of the centerline N-S road. Corner 3.4' E and 5.08' N of CIM. RPs- punched + in top pf lug at top southend 18" CMP in field drive W West 39.05', punched + in top of lug at top end 18" CMP in field drive W NW 49.52'.

5-28-1999 Olmsted County Surveyor found CIM in good condition down 0.6'. Set ref pipe and tied out corner.

6-9-2000 Olmsted County Surveyor set 1" squre pipe w/cap at surface from 1999 tie out.

4-29-2009 Olmsted County Surveyor found 1" square pipe w/cap at surface in good condition.