Certificate of Location of Government Corner

ID#: 450604 **Description:** 1/4 SEC COR 6 7 45 **Date Set:** 9/16/1988 **County:** Olmsted

Section: 06 **Township:** 104N **Range:** 15W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The corner falls 1' south of fence east, 18' west of north-south fence and 22' east of edge of river bank
The monument is down 0.2'
County Survey Disc in north side corner post E 18.20'
Post w/sign 1' south
The corner is located by GPS measurement

Corner History:

8-15-1853 John Quigley, Deputy Surveyor, measured east 37.98 chains on true line between Sections 6 and 7. Set 1/4 section post. RPs - 14" Burr Oak N20°E 58 links (38.28'), 10" Burr Oak S60°W 73 links (48.18').

6-15-1875 Thomas Hunter, Olmsted County Surveyor, (Book A, Pages 285-286, Survey No. 282); 1/4 post missing and no traces of it could be found. Witness trees were also cut down and the stumps could not be recognized. Ran straight line between section corners and set 1/4 section post on line and at prorated government distance.

9-16-1988 Olmsted County Survey Crew dug and found stake set in 1875. Set telspar pipe with Cast Iron Cap at stake location. The corner falls 1' south of fence east, 18' west of north-south fence line and 22' east of river bank. Set post w/sign 1' south. RP - County Survey Disc in north side corner post to fences E-N-S E 18.20'

10-13-2010 Olmsted County Survey Crew found telspar pipe with Cast Iron Cap down 0.2' in good condition and measured its position using GPS.