Certificate of Location of Government Corner

ID#:450606 **Description:** W 1/4 SEC COR 6 45 **Date Set:** 3/12/2009 **County:** Olmsted

Section: 06 **Township:** 104N **Range:** 15W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The corner falls in centerline of N-S twp road and 126' north of centerline of field entrance west
This corner is located by GPS measurement

Corner History:

1853 Gov't Notes, Ball, north between sections 6 & 1; 40.0 set 1/4 section post. RPs- 10" burr oak S 2 1/2 E273 links, 12" burr oal S3 W 270 links.

6-1875 T. Hunter Pg.285 No.282; corner gone, B trees gone, no evidence or knowledge of corner. 16 east set stake.

10-11-1988 Olmsted County Surveyor set 1/2" rod with CIM over it. RPs- 90.72' NE to bottle cap in PP, 156.09' SE to bottle cap in corner post, corner is 1.5' east of centerline N-S twp road.

9-22-1988 Olmsted County Surveyor, 1/16 south of W 1/4 6; found boulder stone and found drag tooth and stake hole. Set drag tooth 3 1/2' deep in stake hole and set stone back at its location. Stake is .56' west and .17' north of traverse nail. Stone is 1.10' west and 1.50' north of traverse nail.

11-30-2000 Olmsted County Surveyor found CIM down 1.5' leaning badly. Removed CIM and found 1/2" rod down 2.8'. Set 6' telspar w/CIC down 1.0' over 1/2" rod.

5-3-2005 Olmsted County Surveyor found cast iron cap on telspar pipe at surface bent. Removed bent portion of pipe and reset down 0.3'.

5-31-2005 Olmsted County Surveyor referenced corner for bridge construction.

3-12-2009 Olmsted County Surveyor set 4' telspar pipe w/Cast Iron Cap down 0.4' from 2005 construction tie out.