Certificate of Location of Government Corner

ID#: 450607 **Description:** NW SEC COR 6 45 **Date Set:** 10/11/1988 **County:** Olmsted

Section: 06 **Township:** 104N **Range:** 15W **Monument Description:** Cast Iron Monument

Reference Ties:

The corner falls 2' north of centerline of E-W twp road and 1' east of centerline of twp road south
The monument is down 0.4'
1/2" rerod N 6.61'
Bottle cap in PP #2850 SW 50.33'
This corner is located by GPS measurement

Corner History:

6-1853 John Ball, Deputy Surveyor, measured north (Variation 8°30' E) 80.75 chains between sections 1 & 6. Intersected 1st Standard Parallel 425 links (280.50') west of 1/4 Section Corner of south boundary of Section 36, Township 105 North, Range 16 West. RPs - 10" Bur Oak S 89° W 540 links (356.40'), 6" Black Oak N 20° E 320 links (211.20')

1875 State law required monuments to be set at township corners. The responsibility for monumenting this corner belonged to Mower County.

6-15-1875 T. Hunter, Olmsted County Surveyor, (Book A, Page 285, No. 282), corner missing and no traces of it could be found. Witness trees also both cut and no traces of the trunks or other evidence could be found. The south 1/4 Section Post of Section 36, T105N, R16W, also missing and no traces could be found. Set temporary 1/4 post midway and on line between section corners. Then measured west 425 links (280.50') of said 1/4 post in accordance with the distance given in the U.S. Field Notes and set stake.

9-21-1988 Olmsted County Survey Crew dug and found 3" diameter black stake mark down 4' and running 2' into clean clay with wood pieces. Set 5/8"x18" rerod in stake hole.

10-11-1988 Olmsted County Survey Crew set Cast Iron Monument over 1/2" rod over 5/8" rod. The corner falls 2' north of centerline of E-W twp road and 1' east of centerline of twp road south. RPs - Bottle cap in PP #2850 SW 50.33', 33.3' south of E-W fence, 1/2" rerod on north edge of road N 6.61'

12-7-2000 Olmsted County Survey Crew found Cast Iron Monument in good condition and measured its position using GPS.

4-29-2009 Olmsted County Survey Crew found Cast Iron Monument down 0.4' in good condition.