Certificate of Location of Government Corner

ID#:510206 **Description:** 1/4 SEC COR 2 3 51 **Date Set:** 11/6/1979 **County:** Olmsted

Section: 02 **Township:** 105N **Range:** 11W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The corner falls 11 1/2' west of centerline of N-S twp road and 2' south of centerline field drive west
County Survey Disk in W side PP NW 133.91'
County Survey Disk in PP #17081 SW 30.91'
This corner is located by GPS measurement

Corner History:

9-1853 Gov't Notes: William A. Jones, Deputy Surveyor. South on true line between sections 2 and 3. 39.61 chs. Set quarter section post. Burr Oak 5 in. N65-1/2°E, 325 lks. Dug trench and planted plum seeds S.E. and S.W. 79.61 chs. To section corner.

11-1891 Thomas Fraser, County Surveyor, (Bk. A, P.462, No.446 and Old Field Bk. 8, Page 1) surveyed in section 2 but "Did not look for this corner . "

4-1892 Thomas Fraser (addition to Bk. A, P.462, No.446 and Old Field Bk. 8, P.20) "Nothing could be found here as the road was graded down and washed out. Set stone on line and midway between C (N. Sec. Cor. 2-3) and E (Sec . Cor. 2-3-10-11) that is divided the measurement according to Gov. Survey. " He used this corner to set the, 1/16th East, a 8" x 2.5" x 20" stone, and the Center 2, a 4x6x30" stone .

4-1892 Thomas Fraser (Bk. A, P.483, No.460 and Old Field Bk. 8, Page, 18) used this corner to set the Center 3.

9-3&5-1975 County Surveyor dug for 1/4-cor. 2-3. Found a 2 x 4.5 x 24" limestone lying flat in the road fill. Dug further and found a mark in clay where it had stood. Set the stone back over the mark. The stone came very near double the line and measure from the pipe set in the post stub at the Center 2 over Fraser's stone found at the 1/16th West.

11-6-1979 County Surveyor set a square pipe (telspar) with a Cast Iron Cap driven over a 0.5" pipe as the corner on the North edge of the stone found in 1975. This Corner is set at prorated Gov't measure (by electronic traverse computation) and also came on the line from Sec. Cor. 2-3-10-11 to N. Sec. Cor. 2-3 (see Certificates on these corners).

7-27-1998 County Surveyor found Cast Iron Cap on telspar pipe in good condition down 1.5' field drive West.