Certificate of Location of Government Corner

ID#: 510209 **Description:** SEC CEN 2 51 **Date Set:** 8/29/1975 **County:** Olmsted

Section: 02 **Township:** 105N **Range:** 11W **Monument Description:** Note: Information regarding this center of section is provided for reference purposes only. A professional land surveyor should make the decision whether to use any existing survey monument or the computed intersection of quarter lines.

1" pipe

Reference Ties:

The corner falls 1' east of corner post to fences north and west
The monument is down 0.5'
This corner is located by GPS measurement

Corner History:

11-13-1891 Thomas Fraser, County Surveyor, (Book A, Pages 462-463, Survey No. 446) set 4"x6"x30" stone on north-south quarter line and in line with old fence west.

4-11-1892 Thomas Fraser, County Surveyor, (Book A, Pages 462-463, Survey No. 446) finished survey and moved 4"x6"x30" stone to intersecting quarter lines. 1/16th East set stake "midway and on line" to East 1/4. However, shows measurements of 20.11 chains (1327.26') and then 20.09 chains (1325.94') to East 1/4. 1/16th West set 2-1/2"x8"x20" stone midway and on line to West 1/4.

8-29-1975 County Surveyor found 8"x10"x30" stone broken in two - one piece on each side of corner post. Dug for mark but could not find it. Found remains of old post 1' east and another on NE side of present post. Set 1" pipe and pieces of stone at 1' east old post location. 1/16th West visited area and probed, but found nothing.

9-5-1975 County Surveyor 1/16th West found recorded stone (top broken) down 1' and set 1/4" rod on east side. The corner falls 1.85' NW of NW corner of corner post to fences north-south-east. RP - Spike in most westerly of triple Oak ESE 117.15'.

7-28-1998 County Survey Crew found 1" pipe down 0.5' in good condition and measured its position using GPS. The corner falls 1' east of corner post to fences north and west. After all quarter corners were in place this pipe is not on east-west quarter line by ± 4-1/2'.

9-11-2002 Brand & Massey Surveying found and used pipe.

8-18-2014 Joel Thoreson, County Surveyor, recommends using the monumented center of section based on historical use of this position.

10-23-2014 Roger Brand & Associates found and used 1" pipe.