Certificate of Location of Government Corner

ID#:510304 **Description:** 1/4 SEC COR 3 10 51 **Date Set:** 11/17/1998 **County:** Olmsted

Section: 03 **Township:** 105N **Range:** 11W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The monument is up 0.2'
The corner falls 5' east of N-S fence and 14' north of fence east
Post w/sign 1' east
This corner is located by GPS reference stations "Thompson I & II"

Corner History:

8-1853 Gov't notes set 1/4-section post 39.98', 10" Blk. Oak S27°W, 55 links, 5" Burr Oak N49°W, 13 links

4-1892 Thomas Fraser pg 477 no 456 old stone found as corner proned 29.5 links too far south and 5-3/4 links on carefully run line. Adjusted corner to place midway and on line 39.81-1/4 chains. 1/16-east set 2 stones 4x8x25" with glass below.

4-1892 Thomas Fraser pg 483 no 460 found corner pg 477 and 1/16 stone east

6-18-1976 County Surveyor visited corner area. Could not determine location without traverse. 1/16 east - found 2 stones 18" long, 0.5' NE of corner post to fence E-W-S. Set 0.5x24" iron between stones as corner.

11-17-1998 County Surveyor set Cast Iron Cap over telspar pipe at lost position between section corners. This falls on top of dam ± 30' higher than natural ground elevation.

12-6-2011 County survey crew found CIC in good condition