Certificate of Location of Government Corner

ID#:510404 **Description:** 1/4 SEC COR 4 9 51 **Date Set:** 8/12/2003 **County:** Olmsted

Section: 04 **Township:** 105N **Range:** 11W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The corner falls 2' south of centerline of E-W twp road, 1' east of fence north and 1' west of fence south
County Survey Disk in W side brace post NNW 42.54'
This corner is located by GPS reference stations "Ferrier Farms & 510305"

Corner History:

1853 Gov't Notes William A. Jones, Deputy Surveyor West on true line between Sections 4 and 9. 40.08 chs. Set quarter section post. Black Oak 9 in. S421/2ºW 112 lks. Black Oak 6 in. N371/2ºW 104 lks. 80.16 chs. Section corner.

10-1857 E.P. Bircher, Surveyor, per T. Hunter, Deputy, (Old Road Book Road No. 24) surveyed a road running N.E.'ly to 1/4 Cor. 3-4 and Wester'ly to Sec. Cor. 4-5-8-9.

4-26-1878 Thomas Hunter, County Surveyor, (Book A, Page 340, No. 334) "found the remains of old stake in center of road, corresponding with line of fence running South, which Mr. J. Coulson avers was set on line of original 1/4 post when standing in mound, & which stood there until a year or two past. Set stone in its place 22x14x10." He used this corner to set the Center 9, a stake, at intersecting 1/4 lines.

10-14 & 15 -1897 William Fraser, County Surveyor, (Book A. Page 612, No. 556) "Found stone as set at B (1/4 Cor. 4-9) in Survey 334, Page 340 this book." Used this corner to set the 1/16 North, a limestone with a boulder on either side, midway (19.77 chs.) and on line to the Center 4, a stake driven well down with a stone by its side, set at intersecting 1/4 lines. Measured 40.251/2 chs. East to Sec. Cor. 9-10-15-16.

5-22&23-1900 Robert Fraser, Deputy County Surveyor, (Book A, Page 683, No. 607) "found stone as used in a former survey in line with fences running N&S and somewhat on North side of road." He used the corner to set a stake near the Center 9 on line to the S. 1/4 Cor. 9 and under theE-W fence.

6-17-1976 County Surveyor dug with the backhoe for this corner and found a boulder of the recorded size 2' deep and leaning to the S.W. Dug down and took the center of the black mark in the clay beneath the stone as the corner location. Straightened the stone over the mark.

6-22-1976 County Surveyor set a 10" Cast Iron Monument over the stone found. Also found William Fraser's limestone between two boulders at the 1/16 North (1304.26 North) and dug at the Center 4 but could not find Fraser's corner there. Dug at the N. 1/4 Cor. 4 but did not find a corner there.

10-28-1983 County Surveyor found the 10" C.I.M. leaning badly. Removed and replaced with a 16" C.I.M., chipping off top of stone beneath to make room for a longer monument. Measured 2656.33 East to Sec. Cor. 3-4-9-10 (found in 1976).

7-30-2003 County Surveyor found stone down 2.0'. Removed stone.

8-12-2003 County Surveyor set 6' telspar pipe w/cast iron cap down 0.4' at boulder position.