Certificate of Location of Government Corner

ID#:510504 **Description:** 1/4 SEC COR 5 8 51 **Date Set:** 12/27/1982 **County:** Olmsted

Section: 05 **Township:** 105N **Range:** 11W **Monument Description:** 1" square pipe with cap RLS #8952

Reference Ties:

The corner falls 0.2' east of centerline of CSAH 10, 3' south of centerline of twp road west and 2' south of centerline of twp road east
County Survey Disk in CP NE 70.89'
County Survey Disk in PP #1943 SE 64.19'
5/8" re-rod W 80.10'
This corner is located by GPS measurement

Corner History:

9-1853 Gov't Notes William A. Jones, Deputy Surveyor West on true line between Sections 5 and 8. 40.12 1/2 chs. Set quarter section post. Burr Oak 6 in. N38 1/2ºW 392 lks. Dug trench. 80.25 chs. To Section Corner.

9-1857 E.P. Bircher, Surveyor, per T. Hunter, Deputy, (Old Road Book, Road No. 24) used corner to survey roads running East and South.

5-1875 Thomas Hunter, County Surveyor, (Book A, Page 279, No.276, and Old Fieldbook 4, Pages 52 53) "Found stone in center of road set by A. A. Cady and others where the original corner stood." He used this corner to set the Center 8, a 17"x10"x9" boulder at intersecting 1/4 lines. The plat shows a measure West of 40.04 chs. to a 3"x8"x30" stone at Sec. Cor. 5-6-7-8.

10-1897 William Fraser, County Surveyor, (Book A, Page 610, No.555) "Found stone as given in Survey 276, Page 279, which agreed with the N.W. B.T. in course and distance with the U.S. Field notes. Said B.T. standing. Stone 24x5x3" at corner." He set an iron stake midway (20.01 1/2 chs) and on line at the 1/16 West and a short stake driven even with ground with an iron stake by its side at the 1/16 South, midway (19.99 1/4 chs) and on line to a boulder found at the Center 8 said set by Hunter in Survey No.276.

1935 County Highway Department (C.H.D. Book 75, Page 3) found a 2x6x18" 1imestone and boulder 2638.6 South at the Center 8.

6-23-1976 County Surveyor dug and found a 3x5x21" limestone with stake on the South side 19" deep. Set a 1/2"x25" rod on the West side of the stone and a 0.5"x12" rod at the road surface. Also dug for Fraser's iron at the 1/16 West but did not find it.

8-8-1977 County Surveyor took additional references before road grading.

5-1982 County Surveyor, after road graded the County Surveyor found a 5/8" rod at the corner (possib1y County Highway Department) bent over and corner be1ieved to be cut out. Most references destroyed so replaced corner, a 5/8" rod, from 1976 traverse points still in place in road running West and took new references.

12-27-1982 County Surveyor set a 1" square pipe with cap as corner in new concrete on C.R. 10 from references taken 5-1982.

7-23-2003 County Surveyor found 1" square pipe w/cap at surface in good condition.