Certificate of Location of Government Corner

ID#:510505 **Description:** SEC COR 5 6 7 8 51 **Date Set:** 7/23/2003 **County:** Olmsted

Section: 05 **Township:** 105N **Range:** 11W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The corner falls 2' east of centerline of N-S twp road and in centerline of twp road east
E side tele cable metal post NNW 86.05'
Concrete nail in SW side PP #42383 NW 61.10'
Bottle cap in E side TP NE 65.78'
Ref pipe NE 72.49'
This corner is located by GPS measurement

Corner History:

1853 Gov't Notes North between sections 7 and 8. 80.00 chs. Set section corner post. Burr Oak 7" S42ºW 325 lks. Burr Oak 6" N85ºW 258 lks.

5-1875 Thomas Hunter (P. 278 No. 275), County Surveyor, shows 3"x8"x30" stone on plat.

5-1875 T. Hunter (P. 279 No. 276) shows 3"x8"x30" stone at corner.

10-1897 William Fraser (P. 610 No. 555), County Surveyor, found stone P. 279.

9-28-1973 County Surveyor found 3"x8"x30" stone. Broke off top piece of stone and set C.I.M. over bottom. Drove iron and set top piece of stone beside bottom of stone.

7-8-1996 County Surveyor found CIM in good condition 3" deep in crushed rock 150th Ave SE.

5-23-2002 County Surveyor set 1" square pipe w/cap as ref pipe to tie out corner for road regrade.

5-24-2002 County Surveyor removed CIM and found iron rod down 2.4' in good condition.

7-23-2003 County Surveyor set a CIC on a 5.0' telspar pipe down 0.4' from the reference pipe.