Certificate of Location of Government Corner

ID#: 510606 **Description:** W 1/4 SEC COR 6 51 **Date Set:** 2/10/2011 **County:** Olmsted

Section: 06 **Township:** 105N **Range:** 11W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The corner falls 8 1/2' east of centerline of CR 136 and in line with fence west
The monument is down 0.7'
This corner is located by GPS measurement

Corner History:

9-17-1853 J. Ball - Gov't Notes - North between Sections 1 and 6. 40.00 chains. Set quarter section post. RPs - Burr Oak 6 in. S40ºW 146 lks (96.36'). Burr Oak 8 in. N1ºE 175 lks (115.50').

7-4-1856 Thomas Hunter (Book A, Pg. 13, No. 20) County Surveyor used corner and set 1/16th west.

5-21-1875 Thomas Hunter (Book A, Pg. 278, No. 275) found remains of old stake 2 rods east of west road fence. Witness trees grubbed out so could not test stake. Set stone 2" wide by 28" long by 18" wide at bottom in place of stake.

9-24-1973 County Surveyor dug and found recorded stone 9' deep. Drove irons on 2 sides of stone with glass around stone.

9-28-1973 County Surveyor set Cast Iron Monument over 3/4"x4' pipe over stone. RPs - 1" iron (1' north of fence) West 80.0'. Concrete Nail in Punch Hole on top center 36" culvert NNW 125.85'.

7-8-1988 County Survey Crew found CIM in good condition.

7-31-1996 County Survey Crew found CIM down 0.7' on east edge of CR 136 1-1/2' north of fence west and located its position using GPS.

6-11-2009 County Survey Crew found CIM down 0.8' leaning east. Removed CIM and found 3/4" pipe down 2.4' leaning east. Removed 3/4" pipe.

2-10-2011 County Survey Crew set 4' telspar pipe with Cast Iron Cap down 0.4' at previously measured coordinate location.

4-12-2017 County Survey Crew found telspar pipe w/CIC at surface bent. Removed bent section of pipe, drove pipe down and replaced cap.