Certificate of Location of Government Corner

ID#:510704 **Description:** 1/4 SEC COR 7 18 51 **Date Set:** 10/25/2011 **County:** Olmsted

Section: 07 **Township:** 105N **Range:** 11W **Monument Description:** Cast iron cap on telspar pipe

Reference Ties:

The monument is down 0.5'
The corner falls 1' south of centerline of E-W twp road and 15' west of centerline field entrance north and in line with fence south.
This corner is located by GPS measurement.

Corner History:

1853 Gov't Notes West between sections 7 and 18. 39.30 chs. Set quarter section corner. Burr Oak 6" N41/2ºW 173 lks. Burr Oak 8" S76ºE 613 lks. 79.30 chs. To section corner.

5-1875 Thomas Hunter (P. 276 No. 273), County Surveyor, found stone set in center of road by settlers where original stake stood.

9-25-1973 County Surveyor dug and found 3"x8" topped limestone. Drove 5/8"x14" rod by stone with C.I.M. above.

12-11-1987 County Surveyor found CIM in good condition.

2-8-2011 County survey crew found CIM with head broken off.

10-25-2011 County survey crew found CIM down 0.5' with top broken. Removed and found 3"x8"x2' stone directly below in good condition. Removed and replaced with a 6' telspar pipe with cast iron cap.

12-6-2011 County survey crew found cast iron cap in good condition