Certificate of Location of Government Corner

ID#:510705 **Description:** W SEC COR 7 18 51 **Date Set:** 6/12/2009 **County:** Olmsted

Section: 07 **Township:** 105N **Range:** 11W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The monument is down 0.4'
The corner falls 9 1/2' east of centerline of CR 136, in centerline of CR 137 west and 2 1/2' south of centerline of twp road east
20d in W side 20" pine SE 81.0'
Punch hole in SE end 36" CMP SE 29.77'
Punch hole in E end 24" CMP NNE 49.53'
This corner is located by GPS measurement

Corner History:

1853 Gov't Notes North between sections 13 and 18. 80.00 chs. Set section corner post. Burr Oak 5 in. S1°W 323 lks. Burr Oak 10 in. N15°W 154 lks. Burr Oak 10 in. S68°E 145 lks. Burr Oak 8 in. N2°E 321 lks.

1857 Thomas Hunter (P. 82 No. 123), County Surveyor, used corner.

5-1875 T. Hunter (P. 276 No. 123) states corner gone. Reset with 3"x9"x36" stone from 3 remaining bearing trees (NE gone).

5-1875 T. Hunter (P. 277 No. 274) found stone P. 276.

9-25-1973 County Surveyor dug with backhoe and found recorded limestone down 5.5'. Set iron and glass around stone with 5/8"x13" rod riser. Set CIM over all.

12-17-1998 County Surveyor found CIM gone due to culvert replacement project.

12-18-1998 County Surveyor set 5/8" rerod at CIM location from traverse reference.

12-19-1998 GGG Inc. found and used monument in survey of NW 1/4 section 18.

6-12-2009 County survey crew found 5/8" rod down 1' in good condition. Took ties and set 3' telspar pipe w/Cast Iron Cap down 0.3' over rod.

2-8-2011 County survey crew found CIM in good condition