Certificate of Location of Government Corner

ID#:510806 **Description:** 1/4 SEC COR 7 8 51 **Date Set:** 11/8/2006 **County:** Olmsted

Section: 08 **Township:** 105N **Range:** 11W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The corner falls in centerline of N-S twp road and in line with fence east
Concrete nail in SW side PP #2834 NW 55.50'
Concrete nail in E side PP #2096 SSW 158.7'
This corner is located by GPS measurement

Corner History:

1853 Gov't Notes North between sections 7 and 8. 40.00 chs. Set quarter section post. Burr Oak 4 in. N88ºE 72 lks. Burr Oak 6" N21ºW 79 lks.

5-1875 Thomas Hunter (P. 279 No. 276), County Surveyor, found stake in the center of the road. Set stone 3"x10"x13".

10-1897 William Fraser (P. 610 No. 555), County Surveyor, found 3"x10"x13" stone P. 279. Reset with stone 3"x6"x30".

9-28-1973 County Surveyor dug and found 3"x6"x30" stone down 10". Broke off top part of stone and set C.I.M. over bottom. Set top piece beside bottom part.

11-8-2006 County Surveyor found CIM down 0.5' with head broken off in good condition. Took local ties and removed. Found stone down 2' in good condition. Removed stone. Set a 6' telspar pipe with CIC down 0.5' at CIM location.