Certificate of Location of Government Corner

ID#:510904 **Description:** 1/4 SEC COR 9 16 51 **Date Set:** 5/1/2007 **County:** Olmsted

Section: 09 **Township:** 105N **Range:** 11W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The corner falls in line with fence north, 140' east of center of creek and 50' south of Oak tree fence junction
Post w/sign 2' east
This corner is located by GPS reference stations "Chase C & D"

Corner History:

Gov't notes: Set 1/4-sec-post 40.05 chs. 10" Burr Oak N89ºE, 85 lks. 10" Linden N87ºW, 170 lks.

4-26-1878 T. Hunter pg 340 no 334 corner in dispute. Set new marked stake. Corner lies considerable south of straight line.

5-22-1900 Robert Fraser pg 683 no 607 above stake gone, ground stony. But settlers all agreed within foot of where corner originally lay. On running line from N1/4 sec 9 over center stake it came just as close. Drove dry Oak stake with 1.5x6x15" stones on each side. 18" J. Oak N32-1/2ºE, 3 lks. 14" Butternut N87-1/2ºW, 29 lks.

5-1-2007 County Surveyor dug at location of main line of fence from east and quarter line from north which fit R. Fraser (1900) witness trees which are now 21" dead Red Oak NE and 18" Butternut stump west. We found 2 vertical stones with stake hole between down 1' on steep slope. Set cast iron cap on telspar pipe in stake hole between stones.