Certificate of Location of Government Corner

ID#:511204 **Description:** 1/4 SEC COR 12 13 51 **Date Set:** 9/21/1998 **County:** Olmsted

Section: 12 **Township:** 105N **Range:** 11W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The corner is up 0.3'
The corner falls on east side of corner post and in line with fences E-W-S
Sign on CP 1/2' west
This corner is located by GPS reference stations "Rose & Blahnik"

Corner History:

8-1853 Gov't notes: Set 1/4-sec-post, 39.97 chs. 10" Burr Oak S89-1/2ºE, 436 lks. 8" Burr Oak, W 224 lks.

5-1889 Thomas Fraser-corner gone but bearing trees were found for stumps with the marks plainly showing on one. Set stake for purpose of this survey at the corner of the fences in line with the fence running South.

9-21-1998 County Surveyor dug for stake set by T. Fraser, we found 8" x 8" post mark below existing corner post. We scraped mark to its bottom and found 2" diameter stake mark running well into clay. Set Cast Iron Cap on 4' long telspar pipe at stake mark location.

2-16-2011 County survey crew found cast iron cap on telspar pipe in good condition.