Certificate of Location of Government Corner

ID#:511704 **Description:** 1/4 SEC COR 17 20 51 **Date Set:** 12/20/1982 **County:** Olmsted

Section: 17 **Township:** 105N **Range:** 11W **Monument Description:** 1" square pipe with cap RLS #15809

Reference Ties:

The corner falls in centerline of CSAH 10 and 4' south of fence west
Punch mark in N end CMP NE 53.01'
County Survey Disk in PP brace ESE 72.69'
Plastic disc in N side PP WSW 61.39'
This corner is located by GPS measurement

Corner History:

8-1853 Gov't Notes: William A. Jones, Deputy Surveyor West on true line between sections 17 and 20. 40.08 chs . Set quarter section post. Deposited stone and dug trench and pits . Made mound and planted Cherry seeds N.E. and S .W. 80.16 chs To section corner.

6-1899 William Fraser, County Surveyor, (Book A, Page 656, No. 585, and Old Fieldbook 9, Pages 37 42) "Did not find or get any evidence to locate this corner so located corner on line and midway (40.07 1/2 chs .) between Sec . Cor . 17-18-19-20 (found stone) and Sec . Cor . 16-17-20-21 (Set stone from B.T. stumps) and set stone as 1/4 S. corner 24xl4x3"." He used the corner to stake the Center of the road running North and South.

6-1902 William Fraser, County Surveyor, (Book B. Page 40) used stakes set near Center 17 in Survey No. 585 for N S 1/4 line and intersected with E W 1/4 line to set the Center 17, a stake.

1935 County Highway Department (C.H.D. Book 75, Page 7) assumed Corner here.

1935 County Highway Department (C.H.D. Book 83, Pages 16 & 75) set corner 5278.9 South of 1/4 Cor. 8-17 and 2644 East of Sec. Cor. 17-18-19-20 .

1964 County Highway Department (C.H.D. Book 295, Page 10) assumed corner. Set drag tooth.

6-21&28-1976 County Surveyor dug for this corner and found William Fraser's recorded stone. Set 1/2x12" rod over the stone and referenced corner.

8-8-1977 County Surveyor took additional references before road graded.

5-14&25-1982 After road graded the County Surveyor set a 5/8" rod as the corner from references and checked Corner location by traverse from 1/4 Cor. 20 29 to 1/4 Cor. 5 8 as measured in 1976. Corner set 0.14 South and 0.05 West of a 5/8" rod (possibly County Highway Department) found at road surface and removed .

12-20-1982 County Surveyor set 1" square pipe w/cap in new concrete on C.R. 10 from references.

11-8-2006 County Surveyor found 1" square pipe w/cap in bad condition. Drilled out cap and replaced with a new one.