Certificate of Location of Government Corner

ID#:511806 **Description:** W 1/4 SEC COR 18 51 **Date Set:** 7/8/2009 **County:** Olmsted

Section: 18 **Township:** 105N **Range:** 11W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The monument is down 0.6'
The corner falls in centerline of CR 136 and 5 1/2' north of fence west
This corner is located by GPS measurement.

Corner History:

1853 Gov't Notes North between sections 13 and 18. 40.00 chs. Set quarter section post. Built mound with trench, drove charred stake, and planted osage orange seed SE and apple seed NE.

5-1875 Thomas Hunter (P.276 Book A), County Surveyor, states corner gone and no traces or knowledge. Set a 3"x11"x23" stone midway and on line.

5-1875 T. Hunter (P. 277 Book A) found stone P.276.

9-25-1973 County Surveyor dug with tractor and found recorded stone. Lowered stone with 5/8"x14" iron below. Set CIM over all.

12-11-1987 County Surveyor found CIM in good condition.

6-12-2009 County Surveyor found CIM down 1.4' leaning SSW.

7-8-2009 County Surveyor found CIM w/head busted off down 1.3' in good condition. Took ties and removed. Found stone down 2.8' in good condition and removed. Set a 4' telspar pipe w/CIC down 0.5' at CIM location.

3-18-2011 County survey crew found CIC on telspar pipe in good condition.