Certificate of Location of Government Corner

ID#:512004 **Description:** 1/4 SEC COR 20 29 51 **Date Set:** 12/20/1982 **County:** Olmsted

Section: 20 **Township:** 105N **Range:** 11W **Monument Description:** 1" square pipe with cap RLS #8952

Reference Ties:

The corner falls 7.2' west of centerline of CSAH 10, 10' south of centerline of CR 110 east and in line with fence west
County Survey Disk in N side 14" Pine ESE 101.2'
County Survey Disk in PP WSW 48.9'
1/2" rod on S edge of road E 156.42'
1/2" rod on S side of fence W 93.53'
This corner is located by GPS measurement

Corner History:

8-1853 Gov't Notes: William A. Jones, Deputy Surveyor, West on true line between sections 20 and 29. 39.99 chs. Set quarter section post. White Oak 4 in. N87-1/2°E, 79 lks. Dug trench as per instructions. 79.98 chs. To section corner.

6-1857 Thomas Hunter, County Surveyor, (Book A, Page 33, No. 52) possibly used this corner to set the Center 29.

4-1878 T. Hunter (Old Fieldbook, Page 54) set a stake 15 chains South of 1/4-Cor. 20-29 (no description) but not on 1/4-line (1/4 line not run)for line West.

6-1899 William Fraser, County Surveyor, (Book A, Page 656, No. 585, and Old Fieldbook 9, Pages 37-42) "this corner was gone and could not be found so located it on line and midway between the S.W. Cor. 20 (found stone) and the S.E. Cor. 20 (found stone). He used the corner to stake the centerline of the road North.

1935 County Highway Department (C.H.D. Book 83, Page 14 & 75) set the corner midway (2633) and on line between the section corners.

1964 County Highway Department (C.H.D. Book 295) assumed corner.

6-28&30-1976 County Surveyor dug midway and on line between the S.W. Cor. 20 (stone found) and the S.E. Cor. 20 (stone found). Set a 1/2x24" rod as the corner midway and on line between the section corners.

8-8-1977 County Surveyor took additional references before road graded .

11-8-1979 County Surveyor set a 5/8" x 2' rod from 1976 traverse points still in place in road East. Took additional references and checked old references.

5-14-1982 County Surveyor found the 5/8" rod set 11-8-1979 bent over. Removed iron.

5-28-1982 County Surveyor set a 5/8" rod as corner from 1976 traverse points still in place in road East. Checked references.

12-20-1982 County surveyor set a 1" square pipe w/cap in new concrete on CR 10 from 1976 traverse points still in place in road East and checked references.

11-8-2006 County Surveyor found 1" square pipe w/cap at surface in good condition.