Certificate of Location of Government Corner

ID#:512104 **Description:** 1/4 SEC COR 21 28 51 **Date Set:** 8/8/2006 **County:** Olmsted

Section: 21 **Township:** 105N **Range:** 11W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The corner falls 32' south of centerline of CR 110 and 5' east of centerline of twp road south
"T"-cut in NE corner of concrete box culvert N 45.32'
Punch hole in SW end 24" CMP WNW 60.60'
This corner is located by GPS measurement

Corner History:

8-1853 Gov't Notes: William A. Jones, Deputy Surveyor. West on true line between sections 21 and 28. 40.06 chs. Set a quarter section post. Burr Oak 7 in. S88°W, 1266 lks. Burr Oak 4 in. N41°E, 21 lks.

4-20-1878 Thomas Hunter (P.337 No.331), County Surveyor, states the corner comes in a road washout. Set a 3"x15"x25" stone midway and on line.

4-25-1878 T. Hunter (P.338 No.332) found the corner P.337.

7-7-1976 County Surveyor dug with the backhoe for the corner but did not find anything.

7-13-1976 County Surveyor set a C.I.M. over a 1/2"x2' rod midway and on line as per Hunter's Survey No.331.

7-11-1994 County Surveyor found CIM down 18" deep in fill of Twp Rd grading to south. Took new references. RP's: Punch hole in SW end 24" CMP WNW 60.60, Punch mark in NE end 24" CMP NNW 63.49.

8-8-2006 County Surveyor found CIM down 1.6' leaning slightly NE. Took local ties and removed monument. Found 1/2" pipe below CIM and took local ties. Drove 6' telspar pipe over 1/2" pipe location. Corner is down 0.4' and falls 31.5' south of CR 110 & 5' east of 165th Ave SE.

11-9-2006 County Surveyor found telspar pipe w/CIC down 0.4' in good condition. Elm tree is gone, NE end of CMP destroyed, tie in SW end ok, did not check. Did not look for concrete culvert.